



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2024/ 249

Dated: 16105 /2024

To,

The Principal, S.S.D. Saraswati Bal Mandir Sr. Sec. School, Road No. 70, West Punjabi Bagh, New Delhi - 110026.

Sub: - Inspection report in respect of S.S.D. Saraswati Bal Mandir Sr. Sec. School Located at Road No. 70, West Punjabi Bagh, New Delhi-110015.

Sir,

With reference to your Email dated 30/03/2024, on the subject cited above. In this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 03/05/2024 in the presence of Sh. Deepak Kumar to see the functioning of the fire safety equipments provided in the building.

During inspection, it has been observed that the said school is comprised of Ground + Three Upper Floors & Basement was issued FSC vide letter No. F6/DFS/MS/School/WZ/632 dated 24/08/2021. Fire safety arrangements such as, Fire Extinguishers, First Aid Hose Reels, Internal Hydrant, MOEFA, Terrace pump, Overhead Tank etc. are provided.

However, following shortcomings were observed: -

1. First Aid Hose Reels are provided but not functional.

2. Terrace fire pump capacity of 450lpm is provided but not functional.

3. Overhead tank capacity of 15,000ltr is found empty.

4. Exit signages is found removed at some places.

In view of above shortcomings, the application for renewal Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Statutory Authority may take suitable necessary action as deemed fit.

Director

Copy to:-

1. The Directorate of Education Old Secretariat Delhi - 110054.

15/ Wed