

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/GH/2024/SZ/ 285
To

Dated: 30/05/2024

The Addl. Commissioner of Police,
Lic/Branch, 1st Floor, P.S Defence Colony
New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s Shyama International located at C-5/32, Safdarjung development Area, New Delhi- 110029.

Sir,

This has reference with **MHA Portal ID 2024051507598 dated 15/05/2024** on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 24.05.2024 in the presence of Mr. Umesh Kumar of the Guest House. During the inspection, it was observed that the Guest House is running Ground plus Three Upper Floors. The shortcomings observed are as below:

1. Smoke management system not provided in the building as per clause 7.31 of UBBL-2016
2. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
3. MOEFA found removed.
4. Fire Fighting pump not on auto mode.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE