



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/2024/Hospital/WZ/328

Dated: 14/06/2024

To,

The Medical Superintendent,
Bhagwan Mahavir Hospital,
Pitampura, Delhi-34.

Sub: - Inspection report in r/o Bhagwan Mahavir Hospital , Pitampura, Delhi- 110034.
Sir,

As per directions of the Competent Authority, it is to inform you that the surprise inspection of above said Hospital building has been carried out by officer concerned of this department on 12.06.2024 to see the compliance of the requisite fire safety measures. Sh. Tatsat Mishra (J.E. Electrical) was present at the time of inspection.

During the course of inspection it was observed that the building comprised of Basement, Ground & Four upper floors. Following shortcomings were observed at the time of inspection:-

1. Door closers of fire check found removed at some places.
2. Hose boxes found without hose pipes.
3. Smoke ventilation in basement found provided but not functional.
4. Detectors found removed at some places.
5. Yard hydrants found provided but not functional.
6. Pressurisation of lift lobby in basement found provided but not functional.
7. Pumping system not found in automation.

You are advised to rectify the above-mentioned shortcoming under intimation to this department, till than the occupancy of the Building/ Premise in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours Faithfully

(Atul Garg)
Director

Ph. 011-23414000

Copy to :-

1. E mail id < msmbh@nic.in >

De a 5