



No: F.6/DFS/MS/2024/Hospital/WZ/ 335

Dated: 15/06/2024

To,

The Medical Superintendent, Satyawadi Raja Harishchandra Hospital, Plot No. 30, Sec-7 A, Narela, Delhi-40.

Sub: - Inspection report in r/o Satyawadi Raja Harishchandra Hospital, Plot No. 30, Sec-7 A, Narela, Delhi-40. Sir,

As per directions of the Competent Authority it is to inform you that the surprise inspection of above said Hospital building has been carried out by officer concerned of this department on 11.06.2024 to see the compliance of the requisite fire safety measures. Sh. S.N Sharma (Supervisor, Electrical) was present at the time of inspection.

During the course of inspection it was observed that the building comprised of Basement, Ground & Four upper floors. Following shortcomings were observed:

- 1. Internal road of 6 m found obstructed by new construction.
- 2. Door closers of fire check doors found removed.
- 3. Fire check door in basement found broken.
- 4. MOEFA found provided but not functional.
- 5. Hose boxes found without hose pipes.
- 6. Pumping system not found in auto mode.
- 7. Fire control room and patient registration room shall be separate.

You are advised to rectify the above-mentioned shortcoming under intimation to this department. Till than occupancy of the Building/ Premise in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours Faithfully

Director

Ph. 011-23414000

01, 20

Copy to :-

1. The Executive Engineer, PWD (Electrical), HMED, North Dr. BSA Hospital, Sec. 6, Rohini Delhi-110085