

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No. F6/DFS/MS/School/NDZ/2024/ 35 2

Dated: 21/06/2024

To,

The Manager,
David Modal Sr. Sec. School
Main Road Tukmirpur,
Delhi - 110094.

Sub: - Regarding grant of Fire Safety Certificate in r/o David Modal Sr. Sec. School located at Main Road Tukmirpur, Delhi - 110094.

Sir,

This has a reference to your email dated 04/06/2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 11/06/2024 in the presence of Mr. Rambir Singh (Manager) and observed that building comprised of (Ground plus three upper floors) old block & (Ground plus three upper floors) New block.

## Following shortcomings were observed during time of inspection:

- 1. All Fire Extinguishers are empty.
- 2. First-Aid-Hose Reel provided but not functional.
- Fire pump of 450 LPM provided but not functional.
- 4. Overhead tank capacity 10,000 liters not provided in each blocks.
- 5. Exit & floors Signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

& DELHI FIRE SERVICE

Copy to:-

1. The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.

2. The Manager, David Modal Sr. Sec. School located at Main Road Tukmirpur, Delhi - 110094.