



No: F.6/DFS/MS/2024/Hospital/WZ/338

Dated: 18/06/2024

To,

The Medical Superintendent, Maharishi Valmiki Hospital,

Sub: -Inspection report in r/o Maharishi Valmiki Hospital (Old Block), Pooth Khurd Delhi, 110039.

As per directions of the Competent Authority, it is to inform you that the Sir, surprise inspection of above said Hospital building has been carried out by officer concerned of this department on 11.06.2024 to see the compliance of the requisite fire safety measures. Sh. Md. Iqbal (A.E. Electrical) was present at the time of inspection.

During the course of inspection it was observed that the building comprised of Basement, Ground & Three upper floors. Following shortcomings

were observed:

1. There are only 3 staircases reaches up to terrace against the requirement of 08 staircases up to terrace.

Lift and staircases are not segregated with fire check door/ removed.

3. Pressurisation of lift shaft found removed.

4. Detector system panel found under maintenance.

Detectors found removed at some places.

Battery backup found removed.

Pumping system not found in automation.

You are advised to rectify the above-mentioned shortcoming under intimation to this department, till than the occupancy of the Building/ Premise in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours Faithful

011-23414000

Copy to :-

1. The Executive Engineer, PWD, North, Dr. B.S.A. Ambedkar Hospital, Sec. 6, Rohini, Delhi-110085.

2. E mail id < msmbh@nic.in >