

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/GH/2024/SZ/360
To

Dated: 24/06.../2024

The Addl. Commissioner of Police,
Lic/Branch, 1st Floor, P.S Defence Colony
New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s Lloyd House Guest House at 13/3, Kalkaji,
New Delhi -110019

Sir,

This has reference with MHA Portal ID 2024052208000 dated 22-05-2024 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 19.06.2024 in the presence of Mr. Dharambir Singh (Gen. Manager) of the Guest House. During the inspection, it was observed that the Guest House is running Ground plus Two Upper Floors. The shortcomings observed are as below:

1. Smoke management system not working.
2. First aid hose reel provided but found not working.
3. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
4. Automatic sprinkler system provided but found not working.
5. Terrace level fire fighting pumps provided but found not working.
6. Overhead tank capacity 5,000 ltrs provided against the required capacity 10,000 ltrs.
7. Exit Signage found removed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE