

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6 /DFS/MS/Educational/SZ/2024/ 415

Dated: 24/07/2024

To,

The Owner/Occupier/Manager,
M/s Periyar Management & Computer College,
Plot No. 1 & 2, Institutional Area, Jasola, New Delhi-25

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Periyar Management & Computer College located at Plot No. 1 & 2, Institutional Area, Jasola, New Delhi-25.
Sir,

With reference to the your letter bearing outdoor diary no. 2898 dated 12.06.2024 on the subject cited above, it is informed that the said building was inspected by a team of officers concerned of this department on 13.07.2024 in the presence of Mr. Parveen (Admin. Officer) and it was observed that the building is comprised of Basements + Ground + 03 upper floors. During the inspection following shortcomings were observed:

- 1. Basement is not segregated properly by fire resistant material.
- 2. Hose reel & internal hydrant systems found non functional.
- 3. Automatic sprinkler system found non functional.
- 4. Terrace Fire pump of 1620 LPM found removed.
- 5. Available terrace jockey fire pump of 900 LPM found non functional.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithful

Pirector

Copy to:-.

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.