

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/2024/ 435

Dated: 05.08/2024

To,

Dr. Malya Saha
Chief General Manager (Electrical & Maintenance),
Delhi Metro Rail Corporation Ltd.,
Barakhamba Lane, New Delhi.

Sub: Renewal of FSC (Fire Safety Certificate) in r/o Under Ground Metro Station, ITO, New Delhi.

Sir,

This has reference to your letter no. **DMRC/O&M/Fire/NOC/L-6/2024/07/01** dated **04.07.2024**, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on **25/07/2024** in the presence of Mr. Krishan Murari and following shortcomings were observed: -

1. Detectors found removed at gallery of ECS plant room and also some detectors found nonfunctional. Further, detectors are also required to be provided at cable trench.
2. Smoke venting arrangements are not connected with detection system.
3. Door closer found removed from fire check door due to that compartmentation is ineffective.
4. Electrical shafts are not sealed properly horizontally & vertically which are required to be sealed properly to restrict the fire to be spread .

Hence, Fire Safety Certificate (FSC) cannot be issued at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings for further consideration in the matter.

Yours faithfully,

(Anil Garg)
DIRECTOR
Delhi Fire Service