

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2024/SZ/ 450
To

Dated: 14/08/2024

Mr. Chandra Bhan Singh Chauhan,
Building No 05, Somdatt Chamber-I,
Bhikaji Cama Place, New Delhi 110066

Sub: Regarding issuance of Fire Safety Certificate in r/o M/s Building No 05, Somdatt Chambers-I, Bhikaji Cama Place, New Delhi 110066

Sir,

This has reference with letter no EM/SDC-I/Fire/2024/(1) dated 18/06/2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said building have been carried out by the officer concerned of this department on 12/08/2024 in the presence of Mr. Chandra Bhan Singh and observed to verify the fire safety measures installed in the building. During inspection, following points were observed:

1. The Fire Check door found removed at some places.
2. Smoke management system found removed in the basement.
3. First aid hose reel provided but found not working.
4. Detection system found removed at some places.
5. MOEFA provided but found not working in basement.
6. Public address system not working.
7. Automatic sprinkler system not working and sprinkler head found cover under false ceiling. Sprinkler system need to be extended in left out area.
8. Internal and yard hydrant provided but found not working.
9. Fire fighting pumps not working.
10. Exit signage found removed at some places.
11. Electrical meter needs to be removed from staircase.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours Faithfully,

(ATUL KARS)
DIRECTOR

DELHI FIRE SERVICE