

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/2024/SZ/ 452  
To

Dated: 14/08/2024

Mr. Anup Singh,  
Under Secretary to the Govt. of India,  
Plot No 14, HIDCP Vishala Building,  
Bhikaji Cama Place, New Delhi 110066

Sub: Regarding issuance of Fire Safety Certificate in r/o Plot No 14, HIDCP Vishala Building, Bhikaji Cama Place, New Delhi 110066

Sir,

This has reference with letter no nil dated 31/07/2024 received through outdoor diary no 4809 dated 01/08/2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said building have been carried out by the officer concerned of this department on 12/08/2024 in the presence of Mr. Sumit and observed to verify the fire safety measures installed in the building. During inspection, following points were observed:

1. The Fire Check door found removed at some places.
2. Smoke management system found removed in the basement.
3. First aid hose reel provided but found not working.
4. Detection system found removed at some places.
5. MOEFA provided but found not working in basement.
6. Public address system not working.
7. Automatic sprinkler system not working and sprinkler head found cover under false ceiling. Sprinkler system need to be extended in left out area.
8. Internal and yard hydrant provided but found not working.
9. Fire fighting pumps not working.
10. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours Faithfully,

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

6/11/24