

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTER: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/2024/ 530

Dated: 16 08 24

To,

The Principal,
Maxfort School Building,
Hindustan Co-op Housing Building Society
Guru Harkishan Nagar, Paschim Vihar,
New Delhi-110087.

Subj.:- Regarding renewal of Fire Safety Certificate in respect of Maxfort School Building, located at Hindustan Co-op Housing Building Society, Guru Harkishan Nagar, Paschim Vihar, New Delhi-110087.

Sir,

Please refer to your letter no. nil dated 30/07/2024 on the subject cited above. In this connection, it is to inform you that the above said school building was inspected by the officer concerned of this department on 02/08/2024 in the presence of Sh. Deepak Yadav (Administrator). During inspection, it has been observed that the school building is comprised of basement, Stilt, Upper Ground, 1st, 2nd & 3rd floors only. However, the following shortcoming has been observed:-

- 1. First Aid Hose Reel found non-functional.
- MOEFA found non-functional.
- 3. PA system found non-functional.
- 4. Internal Hydrants found non-functional.
- 5. Fire pump of 2280 lpm & Terrace pump of 900 lpm found non-functional.

In view of the above shortcomings, the application for renewal of Fire safety Certificate cannot be considered at this stage & rejected. You are advised to rectify the above mentioned shortcoming under intimation to this department for taking further necessary action.

Yours faithfu

Ajul Garg)

W.

Copy to:-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054