

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/2024/WZ/ School | 588

Dated: 03/09/2024

To,
The Executive Engineer (E),
PWD Edu. Elect. Edn. Div. (N),
ITI Campus, Pusa, New Delhi- 110012.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Co-ed Sr. Sec. School located at
Ladpur, Delhi- 110081.

Sir,

This has reference to your e mail id dated 13/08/2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said educational building has been carried out by the officer concerned of this department on 23.08.2024 to see the compliance of requisite fire safety measures. Sh. N.K. Deewan & Sh. Karnail Singh (Electrical Engineer) were present at the time of inspection.

During the course of inspection it was observed that the building comprised of Ground and 04 upper floors. Your request for issuance of FSC is rejected as the following shortcomings were observed:

1. Fire Check doors are not provided as marked on building plans.
2. Lift lobbies are not segregated with fire check doors.
3. MOEFA not provided as per clause 9.3.9 of UBBL- 2016.
4. Terrace level pump not found in auto mode.
5. Overhead tank of 20,000 ltrs capacity shall be made of steel/ RCC.
6. Standby power supply found not provided.
7. Fire control room not provided.
8. Electrical panel of MP Hall shall be removed from the corridor or been segregated with fire check door.

Keeping in view of above shortcoming Fire Safety Certificate is not considered at this stage and rejected. You are advised to rectify the above-mentioned shortcomings for further consideration in this matter.

Yours Faithfully

(Aul Garg)

Director

Ph. 011-23414000

03/09/24