

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

263



No. F6/DFS/MS/WZ/2024/College | 282
To,

Dated: 02/09/2024

Sh. Ajay Bindal,
Strength India Educational Society (Reg.),
AU Block, Outer Ring Road,
Pitampura, Delhi-110034.

Sub: - Inspection report in r/o Vivekanand Institute of Professional Studies located at AU Block, Pitampura, Delhi- 110034.

Sir,

This has reference to your application no. SIES/AS/VIPS/DFS/2K24/0441 dated 05/08/2024 received through outdoor diary number 4968 dated 06/08/2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said educational building has been carried out by officer concerned of this department on 24/08/2024 to see the compliance of the requisite fire safety measures. Sh. Ajay Bindal was present at the time of inspection.


During the course of inspection it was observed that the building comprised of 03 Blocks (A Block = B + G + 07 Upper floors), (B Block = B+G+ 05 Upper floors) & (C Block = B + G + 09 Upper floors). Your request for renewal of FSC is rejected as the following shortcomings were observed:

1. Fire check doors found locked at some places.
2. Electrical shafts are not sealed at some places.
3. Detectors found removed at some places.
4. MOEFA found provided but not functional.
5. P.A. system found provided but not functional.
6. Pumping system not found in auto mode.
7. Exit signage's found removed at some places.
8. Pressurization of lift shaft and lift lobby found provided but not functional.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,


(Atul Garg)
Director


29/8/24