

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/School/2024/SZ/Go7

Dated: 06/ 09 /2024

The Executive Engineer (Bldg) HQ, 9th floor, Civic Center, Minto Road, New Delhi 110002.

Sub: - Regarding issuance of Fire Safety Certificate in r/o M/s A.H.S.S & Amrita Vidyalayam, Sec-7, Pushp Vihar, M.B. Road, New Delhi-110017.

Sir,

This has reference to with **Online ID 10063121 Dated 27/08/2024** on the subject above. In this connection, this is to inform you that joint inspection of the premise was conducted by the team of officers from Delhi Fire Service on 03/09/2024 in the presence of Mr. Vipin Kumar (JE/Bldg/MCD) to check the compliance of fire safety arrangements from fire safety point of view and following shortcomings were observed:

- The Road width for fire tender movement at one side is less than of 06 mtr.
- 2. The widths of staircases are between 1.40 mtr to 1.45 mtr wide against the required width of 1.50 mtr each.
- Fire check doors not provided some position at staircases as marked on building plan.
- 4. MOEFA not working.
- 5. Exit Signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(ATTUL GARG)
DIRECTOR

DELHI FIRE SERVICE