



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 640

Dated: 19/09/2024

To,

The Principal,
Shri Ram D.A.V. International School
At Nathupura, Delhi-110084.

Sub:- Regarding renewal of fire safety certificate in r/o Shri Ram D.A.V. International School located at Khasra No- 3/2/1, Gali No-9, D-Block, Nathupura, Burari, Delhi-110084,
Sir,

Please refer to your letter no-SRDS/2024/Fire/01 dated 04.09.2024 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 13.09.2024 and building was comprised of ground & first floors only to verify the compliance of the shortcomings/ observations already communicated by this department vide letter of even no.F6/DFS/MS/2024/School/615 dated 10.09.2024 and observed that the shortcomings have not been removed so far.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage.

Yours faithfully

(Arul Garg)
Director

Ph: 011-23414000

13/9/24



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 615

Dated: 10/09/2024

To

The Chairmen
Shree Ram Dav International School,
Kh. No- 3/2/1, Gali No-9, Block-D, Nathu Colony,
Nathupura, Burari, Delhi-84.

Sub: - Regarding grant of fire safety certificate in r/o Shree Ram Dav International School located at Khasra No- 3/2/1, Gali No-9, Block-D, Nathu Colony, Nathupura, Burari, Delhi-110084.

Sir,

Please refer to your letter no- nil dated 27.08.2024 on the subject cited above. In this connection this is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 03.09.2024 in the presence of Mrs. Poonam (Incharge) was also present at site to check the existing fire safety measures & means of escape measures. During inspection it has been observed that the school premises is comprised of ground & first floor only. The observations/ shortcomings made are as under:-

1. The School class room doors size is provided 90cm against the requirement of 1.20m.
2. Hose reel hose is not provided.
3. Terrace level fire pump capacity of 450lpm is not provided.
4. Terrace level fire water tank capacity of 10,000ltr is not provided..
5. Exit & floors signage's is not provided at strategic location in the school building.
6. Standby power supply is not provided.
7. As built plan of the school duly signed by registered architect & owner shall also be submitted.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of school premises is at your own risk & responsibility.

Yours faithfully

(Atul Garg)
Director

Ph:-011-23414000

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.