

dsy

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No. F6/DFS/MS/School/2024/ 692

Dated: 09/10/2024

To
School In charge /HOS,
Govt. Boys Sr. Secondary School
Mata Sundari Road, 23, Deen Dayal Upadhyay Marg,
New Delhi.

Sub: Regarding issuance of FSC in r/o Govt. Boys Sr. Secondary School located at Mata Sundari Road, 23, Deen Dayal Upadhyay Marg, New Delhi.

Sir,

This has reference to your letter no. GBSSS/MSR/2024-25/147 dated 27/08/24, on the subject cited above. In this regard, it is to inform you that the site was visited by officers concerned of this department on 27.09.2024 in the presence of concerned teacher and following shortcomings are observed.

1. Hose reel is not provided.
2. Overhead tank of 10,000 liter is not provided.
3. Fire Pump of 450 LPM capacity is not provided.
4. Exit signages not provided.

In view of above, fire safety certificate (FSC) cannot be considered at this stage. Therefore, it is requested to rectify the above shortcomings at the earliest for further consideration in the matter. Running school without valid Fire Safety Certificate is at the risk and liability of school management, concerned authority may take action at their end.

Yours faithfully,

(Anil Garg)
DIRECTOR
Delhi Fire Service

Copy to:-

1. The Director (Education), Govt. of NCT, Old Sectt. Delhi - 54.