

C95

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO. F-6/DFS/MS/Educational/2024/SZ/352

Dated 30/10/2024

To

The Executive Engineer (Bldg)-I
Municipal Corporation of Delhi
Green Park, New Delhi 110016

Sub: - Regarding issuance of fire safety certificate in r/o M/s Coaching Centre / Tuition Centre at Plot No 11, Block C-2, Safdarjung Development Area, New Delhi.

Sir,

This has reference to your letter no D/990/EE(B)-I/Bldg/SZ/2024 dated 10/09/2024 on the subject cited above. In this connection this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 19/10/2024 in the presence of Mr. Damodar to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

- 1 There are two staircases having width of 1.16 mtr & 1.50 mtr for ground & upper floor and two staircases having width of 1.16 mtr & 0.70 mtr for basement against the required width of 1.50 mtr each.
- 2 The width of corridor is between 1.40 mtr to 1.50 mtr against the required clear cut width of 1.50 mtr.
- 3 The main exit doors having width of 1.0 mtr against the required width of 1.50 mtr & the class room door width is 0.75 mtr against the required width of 1.20 mtr.
- 4 Smoke Management System not provided in the basement & upper floors.
- 5 First Aid hose reel provided but found not working.
- 6 Automatic sprinkler system provided but found not working in the basement.
- 7 Terrace level fire fighting pump capacity 450 LPM provided against the required capacity of 900 LPM & the pump is not operation.
- 8 Overhead tank capacity 2000 ltr provided against the required capacity 15,000 ltrs.
- 9 Exit signage not provided.
- 10 Lift lobby not provided with fire check door not provided in the basement and upper floors.
- 11 Staff seating area in the basement not allowed.
- 12 Classes' partitions with glass not allowed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(ATIL GARG)
DIRECTOR

DELHI FIRE SERVICE