

C/218

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

NO. F6/DFS/MS/CGHS/SZ/2024/2434

DATED: 01/11/2024

To,

The President,
Sky Lark CGHS, Ltd.
Plot No. 35, Sector – 6, Dwarka, New Delhi.

Subject: Renewal of Fire Safety Certificate in r/o Sky Lark CGHS Located at Plot No. 35, Sector – 6, Dwarka, New Delhi.

Sir,

Please refer to your letter No. Skylark/CGHS/2024/204, dated 20/09/2024 on the subject mentioned above. In this connection it is to inform you that the above said premise was visited by the officer concerned of this department on 22/10/2024 in presence of Sh. Naveen Katarya (Administrator) & Sh. Pankaj to see the compliance of the shortcomings communicated vide this office letter No. F6/DFS/MS/SZ/2022/CGHS/679, dated 25/03/2022 & found that the shortcomings are still not fully complied.

In view of the above shortcomings renewal of Fire Safety Certificate from fire safety point of view cannot be considered. You are directed to comply the shortcomings under intimation with this department for further consideration in the matter.

Yours faithfully,

(Atul Garg)

Director,
Delhi Fire Service

Copy to: - The Joint Director (Building), DDA, Vikas Sadan, INA, New Delhi.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

C.211

No.F6/DFS/MS/SZ/2022/ CGHS/ 679

Dated: 25/03/2022

To,
The Authorized Signatory.
Sky Lark CGHS,
Plot No. 35, Sector – 6, Dwarka.

Subject: Renewal of Fire Safety Certificate in r/o Sky Lark CGHS Located at Plot No. 35, Sector – 6, Dwarka.

Sir,

Please refer to Email dated 20/02/2022 on the subject mentioned above. In this connection it is to inform you that the inspection of the premises was carried out by the team of officers concerned from this department on 14/03/2022 in the presence of Sh. K.K Kapoor (Secretary) for the renewal of fire safety certificate.

During course of inspection the following shortcomings were observed:

1. Six meter wide internal road found not clear.
2. Smoke check Doors found removed in basement.
3. Smoke management system found removed in basement
4. Only one ABC type fire extinguisher of 5kg capacity is found provided at each floor against required two fire extinguishers.
5. Hose reel hose & Hydrant found removed at terrace.
6. Two hoses of 15m length must provided at each floor as per relevant IS code.
7. MOEFA found nonfunctional.
8. PA System found Nonfunctional.
9. Terrace Pump of 450 lpm with 40m head found nonfunctional in auto mode.
10. Exit signage found removed at some places

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

You are requested to comply the abovementioned shortcomings under intimation to this department.

Yours faithfully,


(Arul Garg)
Director
Delhi Fire Service

Copy to:- The Joint Director, DDA, Vikas Sadan, INA, New Delhi. 24/3/22