

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

गुजादी ना आज़ादी ना अमृत महोत्सव

No. F6/DFS/MS/Industrial/NDZ/2024/2506

Dated: 13/11/2024

To,

Mr. Anil Kumar Sharma Plot no. 377, Patparganj Industrial Area, Delhi – 110092.

Subject: - Regarding Fire NOC in r/o M/s Plot no. 377, Patparganj Industrial Area, Delhi – 110092.

Sir,

Please refer to your outdoor dairy no. 8002 dated 18/10/2024 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 09/11/2024 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/NDZ/2022/153 dated 17/01/2022 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: as above

DIRECTOR

C DELHI FIRE SERVICE

Copy to:-

1. The Executive Engineer (Bldg.) HQ, MCD Udyog Sadan, Plot No. 419, FIE, Patparganj, Delhi - 110092.

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/NDZ/2022/ 153

Dated: 17 .01.2022

To

Sh. Anil Kumar Sharma, Plot No. 377, FIE, Patparganj Industrial area, Delhi-92.

Subject:- Regarding renewal of Fire Safety Certificate in r/o Plot No. 377, FIE, Patparganj Industrial area, Delhi-92.

Sir,

This has reference to your email dated 20/12/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 28/12/2021 in the presence of Mr. Anil Kumar Sharma and the following shortcomings were observed:

- Pump of capacity 950 LPM & 450 LPM is provided against required capacity of 2280 LPM & 180 LPM.
- 2. Staircase of 1.50 M is not provided in basement and encroached at upper floor.
- 3. Fire check doors not provided.
- 4. In basement Smoke management system is not provided.
- 5. Lift Signage not provided.

Hence, renewal of Fire Safety Certificate can not be considered at this stage.

Yours faithfully,

(Dr. S. K. Tomar)

Dy. Chief Fire Officer

Delhi Fire Service

o K