

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

अप्रादी वा अप्रादी वा अप्रत गतिसाव

No.F6/DFS/MS/School/2024/NDZ/ 7 86

Dated: 25 / 11/2024

To,

The Principal Govt. Girls Sr. Sec. School Rani Garden, Delhi - 110031.

Subject: - Inspection Report in r/o of Govt. Girls Sr. Sec. School located at Rani Garden, Delhi - 110031.

Sir,

Please refer to your Email dated 27/09/2024 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 14/11/2024 and observed that the shortcoming has still not complied as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2024/347 dated 18/06/2024 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: as above

DIRECTOR
DIC DELHI FIRE SERVICE

Copy to: -

- The Dy. Director of Education, B Block, Yamuna Vihar, Delhi 110053.
- 2. The Manager, Govt. Girls Sr. Sec. School located at Rani Garden, Delhi 110031.



भाषाति मा ।व भाषा मार्ग ।व

No. F6/DFS/MS/School/NDZ/2024/ 347

Dated: 18/06/2014

To.

The Manager, Govt. Girls Sr. Sec. School Rani Garden, Delhi - 110031.

Sub: - Regarding grant of Fire Safety Certificate in r/o Govt. Girls Sr. Sec. School located at Rani Garden, Delhi - 110031.

Sir.

This has a reference to your email dated 03/06/2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 10/06/2024 in the presence of Mr. Rajan Kumar (Principal) & Mrs. Poonam (H.O.S.) and observed that building comprised of two blocks, Block – B Ground plus one upper floor & Block – C Ground plus three upper floors.

## Following shortcomings were observed during time of inspection:

- Two staircase of width 1.40 meter & 1.50 meter are provided against requirements of 1.50 meter each in block - B. Either width of staircase shall be extended an additional staircase of width 1.50 meters shall be provided.
- Fire Extinguishers not provided in block B.
- 3. All Fire Extinguishers are empty in block C.
- 4. First-Aid-Hose Reel provided but not functional.
- 5. Internal hydrants provided but not functional.
- 6. Fire pump of 450 LPM provided but not functional.
- 7. Overhead tank capacity 10,000 liters not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithf

DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.

2. The Manager, Govt. Girls Sr. Sec. School located at Rani Garden, Delhi - 110031.