## 1

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No.F6/DFS/MS/NDZ/2024/ 628

Dated:-2.º///./2024

To,

Sh. Rajeev Kumar Pandey, Section Officer (Admin), 4<sup>th</sup> floor, Aadhaar HQ, Behind Kali Mandir, Gole Market, New Delhi -01.

Sub: Regarding renewal of FSC in r/o Unique Identification Authority of India (UIDAI), Head Quarter Building, at Bangla Sahib Road, New Delhi.

Sir,

This has reference to your letter no. Nil dated 08/10/24 on the subject cited above, it is to inform you that the site was inspected by the officers concerned department on 13/11/24 in the presence of Sh. Ravinder Dubey and the following shortcomings were observed: -

- 1. Pressurization of lift lobby and shaft found nonfunctional.
- 2. Diesel Pump found non functional

In view of above, the case is rejected and fire safety certificate (FSC) cannot be issued at this stage.

Copy to:

The Chief Architect, NDMC Palika Kendra, New Delhi.