



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

cl/3
①②③

No. F6/DFS/MS/WZ/2024/ 825
To,

Dated: 13/12/2024

The Principal,
Adarsh Shiksha Sansthan,
B-2, Block, Ashok Vihar,
Phase-II, Delhi-110052.

Sub: - Inspection report in r/o Adarsh Shiksha Sansthan, B-2, Block, Ashok Vihar, Phase-II, Delhi- 110052.

Sir,

This is in reference to your letter no. A.S.S./32/24-25/01 dated 01/12/2024 received through outdoor diary no. 9774 dated 02/12/2024 on the subject cited above. In this connection, it is to inform you that the above said school building was re-inspected by the officer concerned of this department on 09/12/2024 in the presence of Smt. Kavita Kaushik (Head Administrator) to verify the compliance of shortcomings communicated vide this department letter No. F6/DFS/MS/School/2023/WZ/603 dated 22/12/2023.

The status of shortcoming is as under:-

Sr. No	Shortcomings	Status
1.	The width of staircases for upper floors is 1.40 m & 1.17 m against the required width of 1.50 m each.	Provided 1.50 m & 1.17 m (Not Rectified)
2.	The width of staircase for basement is 1.10 m, 1.20 m & 1.05 m against the requirement of two staircases of 1.50 m each.	Provided 1.50 m, 1.10 m, 1.20 m & 1.05 m (Not Rectified)
3.	Fire check doors not provided in basement	Only provided in 01 staircase (Not Rectified)
4.	Width of corridor found obstructed by metal gates which has to be removed.	Rectified
5.	Smoke ventilation system not provided in basement.	Rectified
6.	Exit signage's found not provided.	Rectified

In view of the above shortcomings, the request for issuance of Fire Safety Certificate cannot be considered at this stage & rejected. You are advised to rectify the above mentioned shortcomings under intimation to this department for further necessary action in this regard.

Yours faithfully,

(Atul Garg)
Director

Ph. 011-23414000

Copy to:-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-54.