GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI -110001

No FG/DFS/ms/2011/Eh/1988

Dated 12-0x-2011

FIRE SAFETY CERTIFICATE

Certified that the M/S Café Rendezvous at T - 540, Malviya Nagar, New Delhi. Comprised of ground floor was granted NOC by this deptt, vide letter No. F6 / DFS / MS / EH / 2005 / 2720 dated 30- 12- 2005. The premises was re-inspected by the officer concerned of this department on 1-7-2011 in the presence of Mr. Pardeep and found that the said Restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises is fit for occupancy with effect from - 8-2011 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 subject to conditions printed overleaf.

Issued on 12-08-2011 at New Delhi.

Chief Fire Officer

Delhi Fire Service

Copy to :-

 The Authorized Signatory, M/S Café Rendezvous at T – 540, Malviya Nagar, New Delhi.

The Dy. Health Officer
 Health Department, South Zone
 Green Park, New Delhi.

INSPECTION OF THE RESTAURANT

May kindly see the letter dated 09.04.08 in above said reference received from the DHO (SZ). The restaurant was inspected by undersigned to ensure the suitability of the of the existing fire safety measures in the restaurant. Manager with other staff of the restaurant was also present at the time of inspection.

During the course of inspection, it has been observed that the eating house/restaurant is being run at the ground floor with the two exits. The building is accessible to fire engines in case of emergency through a road of sufficient width: The existing fire safety arrangements with respect to the circular no F6/DFS/MS/EH/2005/718 dated 4/4/2005 were found provided such as: - Hose reel, Manual fire alarm, overhead water storage tank, Fire pump, ISI marked fire extinguishers of different type and cap., Emergency Light with battery back up, illuminated Exit signs, smoke venting arrangements, Emergency supply. Electric wiring is concealed type. MCBs/ELCBs on Main and distribution electric circuit were also provided.

The above said equipments/system were checked/operated and found functional at the time of

inspection.

In view of the above said observations of fire safety directives / measures as found during the above said inspection, the fire clearance /NOC for the renewal of license for restaurant part/area may be considered from fire safety angle by this deptt. The letter on above lines is prepared accordingly for approval and signatures (if approved).

Submitted please.

Defo III Reily
MS (2" Reily

Ref! - Letter Ho - HIL- dorted 28/11/11 (00,3735)

That— NOC Was granted by this depth viole letter to

16/1005) DES) EN) 2005) 2720 dated 30.12.05 on the basis
of fire protection measures on indicated below.

Provided. As. Access -- Provided Emergency lights - Provided. Exit Signs - Poorided Two Exits. Provided (1.500) Emergency Supply 12 means of Escape - Provided (exhaust forms) 13 Smoke Venting 14. Electric wising conceated Type - Poorided-Further the foremises was reinspected by ADDCORP in the possence of nor Pardiep on 1.7.11 and observed that There is no additional construction in the premises for which HOC was granted by this deptt. All the fire protection arrangements as stated above & which are provided, have been checked and found functional at the time of inspection. In view of the above, renewal of fire Safety Costificate is secommended. Accordingly doubt letter is placed on file for opproval. 5 places bleast. 00 (BCP) Abuty 1

The width of exits shown in inspection report Re out writted please F.T. letter is put up for sign. Please.