GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI-110 001

No. F6/OFS/ms/2011/1993

Dated: 16/08/1

FIRE SAFETY CERTIFICATE

Certified that the MG.S. Hospital at Main Rohtak Road West Punjabi bagh, New Delhi is comprised of basement + ground + 1st Floor + 2nd floor only occupied by Dr. Ashish have complied with the fire prevention and fire safety requirements in accordance with the rule 33 of the Delhi Fire Service Rules, 2010 & verified by the officer concerned of Fire Service on 04.03.2011 in the presence of Director (Dr. Ashish Chandra) and that the building/premises is fit for occupancy Class Group (C-1)(2) (Institutionally building) with effect from [1.6] [1.6]. In for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 16/08/11 at New Delhi by.

DIRECTOR Delhi Fire Service

Copy to :-

Dr. Ashish Chandra, Director, M.G.S. Hospital, Main Rohtak Road,
Punjabi Bagh, New Delhi

of chin

May kindly peruse the letter no. nil dated17-01-2011 received from Dr. Chandra regarding NOC from fire safety point of view in r/o M.G.S. hospital loc Rohtak Road west Punjabi Bagh. This hospital issued guide lines vide noF.6.DFS/MS/BP/93/2006/hospital dated 09-12-93. Premises was inspected as DFS Act 2007 rule 2010 and observed that building is comprised of basement + Floor + Ist and 2nd floor and is built upon a 5449 sq. mtrs. Plot, and point wise fire arrangements are as below:-

No.	Fire Safety provisions	Provided/Not Provided	Remarks
1.	Access to building	Abutting 30 mtr. Wide road.	
2.	Number, width type and arrangement of exits	4 staircase are provided 2 are2 mtr wide & 2 other are 1.5 mtr wide & meeting the travel distance.	
3.	Protection of Exits by means of fire check door (s) and or pressurization	Fire check doors are provided as shown in the plan.	/
4.	Compartmentation	Provided	Not mentioned guidelines
5.	Smoke Management System	Exhaust fans are provided in the basement, building is not centrally A.C.	Not mentioned guidelines
6.	Fire Extinguishers	10 A.B.C. Cap. 4.5 kg , 10 Co2 cap. 4.5 kg. and 4 foam type cap. 9 ltrs. , bearing ISI mark are provided.	
7.	First Aid Hose Reels	Provided, 2 hose reels at each floor having 36 mtr. hose reel terminating into a shut off	

nozzle of 5 mm

rumping Arrangements	3 pumps are	
3	provided:- 1)One diesel paump cap. 1620 lpm head 45 mtr. (2) One electric pump cap. 1620 lpm head 45 mtrs. (3) One jockey pump cap. 180 lpm head 45 mtr.	2
aptive water storage for fire ghting		
vit Signage	Provided at stretagic location	
rovision of Lifts	Provided and segregate by way of fire check door	
andby power Supply	Provided, 75 KVA	/
efuge area	Not required	Not mentioned in the guidelines
re Control Room	Not required	Not mentioned in the guidelines.
ecial Fire Protection Systems for otection of Special Risks	Not required	Not mentioned in the guidelines.

iew of the above NOC from fire safety point of view is considered. Form H is put proval and signature please

cto. (on leave)