GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO.F6/DFS/MS/GH/2012/ 1638

Dated: 04/05/12

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel New City Palace located at 726, Motor Market, Jama Masjid, Delhi comprised of ground floor (commercial use), Mezzanine floor (commercial use), first floor (Post Office + staff rooms), second floor (Reception + 10 guest rooms + office), third floor (10 guest rooms) and terrace floor (01 room found sealed) was granted NOC by this department vide letter No. F.6/DFS/MS/GH/09/1218 dated 05-05-2009. The premises was re-inspected by the officer concerned of this department on 07-04-2012 in the presence of Syed Ubeid Ali, owner of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class residential (guest house) for 20 rooms with effect from building is fit for occupancy class residential (guest house) for 20 rooms with effect from the fire prevention and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on <u>at for file</u> at New Delhi by.

Chief Fire Officer For Director Delhi fire service

Copy to: -

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

- 2. The Manager, M/s Hotel New City Palace, 726, Motor Market, Jama Masjid, Delhi Conditions for the validity of fire safety certificate
- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT				
1. Name & address of the building: M/s Hotel New City palace, 726, Molos Mck, 2. Type of Occupancy : Lodging House Jama Masjid, Della. 3. Type of Case : Renewal 4. Details of previous NOC : Letter No. F6 DFs/Ms GH 09/1218 Dated: 05f5 2009 5. Fire Safety directives letter No :				
		364/Addl. C.1	P/Leic (H) Daled	1 23/0/2012
S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Paguinament	Provided at site	Remarks
		Requirement		MR/NMR
1	Access to building	¥		
	 Road width 		12mt	IMR
	• Gate width	_	Directly accessible	MR
	Width of internal road	-		_
2	Number, Width, Type & Arrangement	of Exits		
	a. Number of staircases	-		_
	 Upper Floors 		01	MR being old case & SH. Javes
	 Basements 		-	
	b. Width of staircases	, ,		
	 Upper Floors 	_	0.98 007	can asplared
	 Basements 			- #SP1 4104;
	c. Protection of exits	*	2	-
	• Fire check door	Not required being		_
	 Pressurization 	Not required		_
	e. No. of continuous staircases to terrace	4.		
	g. Width of Corridor		1.500+	mR
	h. Door Size	5 q	0.8021-	MR being old case
		2 2		-
3	Compartmentation.	Not required		

GF - Commercial
Mey floor - Commercial
First floor - Post office + Staff rooms
SF - Reception + 10 Guest rooms + Office.
Terrace / Fourth floor - Of doorm (Seeled)

49

				-
	 Fire check door 			
	 Sealing of electrical shafts 	× 8.		
	 Fire Rating of shaft door 			
	 Water Curtain 			
	• Fire Dampers			
4	Smoke Management System.	Not required		
	• Basements	30 a/c per hour		
	 Upper floors 	12 a/c per hour		
5	Fire Extinguishers			
	Total numbers	Wales Co2-4 Belyke-5	provided	MR
	• Types	osclybe -3	provided	MR
	IS marking	ISI marked	provvided	MR
6	First-Aid Hose Reels.			
	Total numbers on each floor	and fard floor	provided	MR
	• Length of hose reel hose	30 m	provided	MR
	Nozzle diameter	5 mm	provided	101/2
7	Automatic fire detection and alarming	g system.	Not required	
	Type of detectors			
	Location of Main Panel			
	Location of Repeater Panel			
	Alternate source of power			
	Hooters' Location			
	Trooters Bounda			
8	MOEFA	Required	bassiged	MR
9	Public Address System.	Roquired	Provided	MR
10	Automatic Sprinkler System.	Not required	3	
	• Basement	- 2		
	• Upper Floor			
	Sprinkler above false ceiling			
11	Internal Hydrants	Not required		
11	Internal Hydrants	140t required		
	Size of riser/down-comer			



		T				
2	Number of hydrants per floor					
	Hose Box					
12	Yard Hydrants. Not required					
	Total number of hydrants					
	Hose Box					
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump					
4,5	➤ Head of Main pump					
	Number of main pumps					
	Jockey Pump out put	, s ,				
	Jockey pump head					
	Standby Pump out put			-		
	Standby Pump Head					
	Auto Starting/ Manual					
	stopping					
	Pump House Access		45			
	Terrace level		240 LPM	MR		
	Discharge of pump	_	24 mt	MR		
	Head of the pump	-	provided	MR		
	Power SupplyAuto Starting of pump		Starting Switch provided at SF	MR		
14	Captive Water Storage for fire fighting.		recephone			
ę	Underground tank capacity	a				
	Draw-off connection					
	Fire service inlet					
	> Access to tank					
	Overhead Tank capacity	2500 LPM	USOD UPM	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts. Not applicable					
	Pressurization of Lift Shaft			-		

19

m/s Hotel New cily palace, 726, molos market, 2/1

	Pressurization of Lift lobby			
	Communication In lift Car			
	Fireman's Grounding Switch			
	Lift Signage			
17	Standby power supply	1	UKVA	MR
18	Refuge Area. Not requi	ired		
	> Total Area			
	> Location			
19	Fire Control Room Not reg	uved.		
	Detector System Panel			
	Flow Switch Panel			
	PA System Panel			
	Batter backup			
	Building Floor Plans			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	One Bc lyter fire extinguisher provided offer & panel	Me

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation

Signature of the Inspecting Officer
Name (M.K. CHATTOPADHYAY)

Designation :- Assistant Divisional Officer

DO (centop) Boro4//2