GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI - 110001

No: F 6/DFS/MS/2011/ School/ 2305	Dated: 27/06/12
FIRE SAFETY CERTIFICATE	
Certified that the Nigary brait bha liels Ichon Intom Puni delen comprised	I Block P-4
Sulfan Pari (Delen comprised	of Ground + one
Moher floor owned/ Tileds school Complied with the	occupied by N. Gam Barible
Complied with the	e fire prevention and fire
safety requirement in accordance with Director of Education circul	ar Dated:-01/03/2011 and
verified by the officer concerned of Fire Service on (15)	In the presence of
building with effect from 27/86	110 for a nariad of
many accordance with rule 36 unless renewed under rule 37	or sooner cancelled under
Rule 40 and subject to compliance of the conditions under rule 38 Rules, 2010.	8 of the Delhi Fire Service
Issued on 2.7/66///at New Delhi.	
	to be
Copy to:-	Chief Fire Officer
copy to	Delhi Fire Service
1 Re Principal	26/ 8hm
Nigoun Kratibha seleschool	26/0
1 Pul Primite sol N'Gam Kratibha Sille School Block - l-4 Sul Tom Puni Delin.	
2 The Diecson tolu. (Med)	
Livit Could Med	
Minto Road Nobelly.	

Note:-This fire safety certificate is subject to compliance of the condition printed over leaf.

1. All the means of escape shall be kept free of all type of obstruction all the time is

2. All the employees shall be acquainted with the use and maintenance of a fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non — functional of fire safety measures; management

shall be responsible.

4. Any deviation, with regards to construction, electric installation etc. may be got verified from the concerned authorities.

5. Basement shall be used as per MGC

6. This NOC may not be treated in any case for regularizations of unauthorized.

construction, If any,
The owner occupier shall submit a declaration every year in form 'K' provided in
the first schedule of Delhi Fire Service Rules 2010. The form is available on
www.dfs.delhigovt.nic.in

1	Name & address of the building Nigan	n Pratibha Gu	rls school, Block	K-P-4, Sulta
2	2. Type of Occupancy			Puri
3	3. Type of Case : New C	Case/ Renewat		
4		No. Mit	Date	
5	5. Fire Safety directives letter No F-16/E	state/cc/f.safe	ety/1/3298,339	8 df. 1 3/11
(-2012	- 1 /	
7	7. Name of the Inspecting Officers:	O SHYAM	LAL	
8	8. Name and designation of officers Sh. Lokesh Kumar			
	from the building side :	Wheshire		
Ş	P. Year of Construction 1990	o(G+1)		
Ammont	0. Applicant's letter No. : No		5-4-2012	
S.	Minimum Standards on fire	Director of Ed	Provided at site	Remarks
No.	prevention and fire safety U/R 33	Requirement		MR/NMR
Associated	Access to building			
	 Road width 	Accessible	6 m	MSR
	• Gate width	do-	um	MIR
	 Width of internal road 	-do-	6 m	MIR
2	Number, Width, Type & Arrangement	of Exits		
	a. Number of staircases	2	21	mIR
	 Upper Floors 	2	2/	mIR
	Basements	M'L	NiL	
	b. Width of staircases	1.50 m	1.50 mg	m)R
	 Upper Floors 	1.5 m	7-m m)	n)R
	 Basements 	N'L	NIL	
	c. Protection of exits			
	• Fire check door		N/R	
	 Pressurization 			
	e. No. of continuous staircases to terrace	2	2	MSR
	g. Width of Corridor		2.10 m,	miR
	h. Door Size) m	1 m	MIR

3	Compartmentation.		NIR	
William Committee on the Committee of Committee on Commit	• Fire check door		/V / N	
	 Sealing of electrical shafts 			
	 Fire Rating of shaft door 			
	Water Curtain			
	• Fire Dampers			
4	Smoke Management System.		NR	
	• Basements	30 a/c per hour	14)1	
	• Upper floors	12 a/c per hour		
5	Fire Extinguishers			
	Total numbers	300 m Covered orea for one ABC or Co2/2. ISI marked	1 4	m)R
	• Types	ABCOr Coza	CKI ABC	
	IS marking	ISI marked	7129	
6	First-Aid Hose Reels.			
	Total numbers on each floor		NIR	0000 100 100 100 100 100 100 100 100 10
	 Length of hose reel hose 	30 m		496.46 (0) (0) (0) (0) (0) (0) (0) (0) (0) (0)
	Nozzle diameter	5 mm		
7	Automatic fire detection and alarming	g system.	NID	
	 Type of detectors 		1912	
	 Location of Main Panel 			
	 Location of Repeater Panel 			
	 Alternate source of power 			
	Hooters' Location			
	- Hootels Location			
8	MOEFA		NIR	
9	Public Address System.		MIR	
1()	Automatic Sprinkler System.		NR	
	Basement			C

	Upper Floor	
	Sprinkler above false ceiling	
San A	Internal Hydrants	NID
rateviennummen selvis installumi	Size of riser/down-comer	7 1 1 0
	Number of hydrants per floorHose Box	
12	Yard Hydrants.	NILO
	Total number of hydrantsHose Box	1411
13	Pumping Arrangements.	8110
	Ground Level	N/R
	Discharge of main Pump	
	Head of Main pump	
	Number of main pumps	
	Jockey Pump out put	
	> Jockey pump head	
	> Standby Pump out put	
	> Standby Pump Head	
	Auto Starting/ Manual	
TO THE REAL PROPERTY AND ADDRESS OF THE PARTY	stopping	
	Pump House Access	
	Terrace level	
	Discharge of pump	
	Head of the pump	
	Power Supply	
4.4	Auto Starting of pump	
14	Captive Water Storage for fire fighting.	NIR
	Underground tank capacity	/ 1 / 1
	Draw-off connection	

R		
	Fire service inlet	
	. Access to tank	
	 Overhead Tank capacity 	
15	Exit Signage.	MIR
16	Provision of Lifts.	N//
manuscripture on plant to the state of the s	Pressurization of Lift Shaft	19/15
contestination (supplemental) (c) (supplemental)	Pressurization of Lift lobby	
anada respective services	Communication In lift Car	
	Fireman's Grounding Switch	
	• Lift Signage	
17	Standby power supply	NIR
18	Refuge Area.	NC / A
	➤ Total Area	NIF
	Location	
19	Fire Control Room	NIO
	Detector System Panel	17/1
	 Flow Switch Panel 	
en der von de	PA System Panel	
	 Batter backup 	
	Building Floor Plans	
20	Special Fire Protection Systems for	No.
	Protection of special Risks, if any:	NiC

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers......

D. o The Service Rules 2010/ Issue shorteonnings as note

- lear Pt

Shylad 28/5/2012 ASSIH. Divn. Officer (SHYAMLAL)