GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE,

No: F6/OF S/ans/2012/4023
FIRE SAFETY CERTIFICATE

Dated: 26/10/12

Certified that the Blue Triangle Family Hostel, YWCA located at Ashoka Road, New Delhi-110001 comprised of ground floor (Reception + 01 Hall + 01 Staff room + 09 guest rooms), 1st floor (15 guest rooms + 03 stores + 01 office), 2nd floor (15 guest rooms + 03 stores + 02 offices + 01 staff room) Total 39 guest rooms was granted NOC by this department vide letter No. F6/DFS/HQ/GH/2009/3919 dated 29-12-2009. The premises was re-inspected by the officer concerned of this department on 12-10-2012 in the presence of Sh. Jacob George Estate manager and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 39 guest rooms with effect from 2.6./.1.0./...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner dancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 26/10/12 at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi w.r.t. letter No.52980/Addl.C.P./Lic.(H)New Delhi dated10-09-12.
- 2. Manager, Blue Triangle Family Hostel, Y.W.C.A. Ashoka Road, New Delhi
- 3. Medical Officer of Health, Health Department, N.D.M.C. Palika Kendra New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPE	CTION REPORT	Blue Triangle	Family Hos
>	CTION REPORT	Road, New	Delle - Hex
Name & address of the building	3		
2. Type of Occupancy	Pesidential (9	west House)	
2 11	Case/Renewal		
4. Details of previous NOC : Lett	er NoF6/DFS/HQ/	G-H/2009/ Dated	29-12-09
	-NA-	1 /54/9	
S Data Di	12-10-2012		
7 Norman - Cal T	Dos. yadav	(ADO)	- 10 (0.000
8 Name and designation of officers			the state of the s
from the building side	le Jacob Geo	Ege. (Blate	manages
9. Year of Construction	2007 (Starting	3 year)	
10. Applicant's letter No. 524	180/Adle.c. P/Lic		Dellite 10-
Minimum Standards on fire	NBC/BBL	Provided at site	Remarks
prevention and fire safety U/R 33	Requirement		MR/NMR
Access to building		1	old case
 Road width 	Accessible	More than 18.5 Mtss with	6 M.R
• Gate width	- NA-	10 31 020	
 Width of internal road 	-N:A-		
Number Width Town B	and the control of th		
Number, Width, Type & Arrangeme	ent of Exits		
a. Number of staircases			
• Upper Floors	one	Two	M.R
• Basements	-N.A -		
b. Width of staircases	8		9
* Upper Floors	01-20 11/28	01-20 Mtes	M.R ~
Basements	N.A -		
c. Protection of exits	2		Per an internal to the second
Fire check door	- N.A -		A Control of the Cont
Pressurization	-NA-		Andrew to develope agent basenbare, and power a develope year in the second
e. No. of continuous staircases to terra	The Principles of the Control of the	one	M.R
g. Width of Corridor	-N.A-		

- N.A -

h. Door Size

contd:

Blue Tecangle family postel, ywc.A., Ashoka Road, were Delli-110001

C	ompartmentation.			
	Fire check door	-N.A -		Kennedi basa sa sa atau M
	 Sealing of electrical shafts 	-N.A -		The state of the s
	 Fire Rating of shoft door 	-NA-		
	Water Curtain			
	• Fire Dampors	- N.A -		
5	Smoke Management System.			
	• Basements	30 a/c per hour	-N. A - Natural venteral	-N.A.
	• Upper floors	12 a/c per hour	Natural ventera	tion M.
				Management of the state of the
5	Fire Extinguishers			
	 Total numbers 	16 NOZ	16 NOS	m.R
	Types		ABC Type and	M·R M·R M·R
	• IS marking	ISI marked	yes.	M.R
6	First-Aid Hose Reels.		Ţ	
	 Total numbers on each floor 	one	one	M.R
	• Length of hose reel hose	30 m	Provided	M-R
-	Nozzle diameter	5 mm	Provided	m.R
7	Automatic fire detection and alarming system.			
	• Type of detectors	- N.A -		
	Location of Main Panel	-N.A -		10
	Location of Repeater Panel	-N.A -		
	Alternate source of power	-N.A -		
	Hooters' Location	-NA-		
8.	MOERA	yes	Psovided.	M·R
9	Public Address System.	408	Psovided.	M·R
10	Automatic Sprinkler System.		A second	
	Basement	-N.A -		

Blue Tréangle family Hostel, yweA Ashoka Road, new Delle-11000/

	Upper FloorSprinkler above false ceiling	-N.A-		
11 I		-N.A -		The state of the s
A.	nternal Hydrants	A STATE OF THE STA		
	Size of riser/down-comer Number of the state of the sta	-NA-		
 Number of hydrants per floor Hose Box 	-NA -			
1	and II	-NA-	and the second s	
	ard Hydrauts.			
	Total number of hydrants	-N.A-	And the second s	
3 P	Hose Box umping Arrangements.	-N.A -		
		And the state of t	The second secon	
	Ground Level		The district strength of the same strength of the s	The second secon
	Discharge of main Pump	-N.A-		
	Head of Main pump	-N-A-	the major analysis of property and a second	Market Service of the Control of the
, !	 Number of main pumps Jockey Pump out a st 	- N.A -		
	rockey rump out put	- N.A -	on more about the second should be second as the second se	The second section is a second
	Jockey pump headStandby Pump out put	- N.A - - N.A -		
	Standby Pump Head	-NA-	SETT A MARKET CONTROL OF THE PARTY OF THE PA	A CONTRACTOR OF THE PARTY OF TH
	> Auto Starting/ Manual	-NA-		
	stopping	-N.A -	the manufacture of the second	7/5
O. Cont. I Congression in	Pump House Access	- at a		
	• Terra e level	-NA-		
,	> Lischarge of pump	450 LAM	450 LAM	NR -
	> Head of the pump	Hontes	400 LPM	MR
	Power Supply	yes	yes	MA
	> Auto Starting of pump	yes	yes	m.R
4 Ca	aptive Water Storage for fire fighting.	AND ADDRESS OF THE PARTY OF THE	Committee and State of the Annual	
	Underground tank capacity	-NA-	and a deline production control of a deline with the first through the delines are indicated and advantage of	and the second s
	Draw-off connection	-N.A -		1

contd:-

Blue Teiangle family Hostel, Y.W.C.A., Ashoka Road, New Della Hoop.

	 Fire service inlet Access to tank Overhead Tank capacity 	- N.A - - N.A - 3000 littles	3000 lite	e m.e.
1.5	Exit Signage.	yes	3000 lites Provided.	8 M.R V
16	Provision of Lifts.		Teoria ca	/// /
	* Pressurization of Lift Shaft	-N.A-	Management of the State of the	
	 Pressurization of Lift lobby 	- N.A -		
	* Communication In lift Car	- W. A -		
	Fireman's Grounding Switch	-N.A -		
	Lift Signage	-N.A -		
17_	Standby power supply	yls.	2. G. Set	A
13	Refuge Area.		0 4 500	M.L
3. See See See See See See See See See Se	Total AreaLocation	- N.A -		
10	Fire Control Room	-NA-		
CO Later American	Detector System Panel	- N.A -		, ý
	 Flow Switch Panel 	- N.A -		
	PA System Panel	-N.A	×	allina har man sugar di a companya dang pi ya mangalay salaman nga Ashan na pangan pi
	Batter backup	-NA-		
	Building Floor Plans	-NA		
20.	Special Fire Protection Systems for Protection of special Risks, if any:	- W-A -	B *	
* *				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi part Service Rules 2010/ issue shortcomings as noted at serial numbers.

Blue Triangle Family Mother, ywest Ashoka Road, new Delli-1100/

Signature of the Inspecting Officer

Name

Tesignation

Subnitted please

Signature of the Inspecting Officer

Name Shasm vis singh yacker

Designation ADe(e)