## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO.F6/DFS/MS/GH/2013/ 589

Dated: 12/02/13

## **FIRE SAFETY CERTIFICATE**

Certified that Taj & Brothers guest house located at 750, Motor Market, Jama Masjid, Delhi-6 comprised of ground floor (Commercial Use), first floor (35 guest rooms + Reception), second floor (32 guest rooms) & third floor (owner's residence) was granted NOC by this department vide letter No. F.6/DFS/MS/GH/2009/3931 dated 31-12-2009. The premises was reinspected by the officer concerned of this department on 04-02-2013 in the presence of Mr. Abdul Karim, Manager of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class residential (Guest house) with effect from 12 / 02 / 13 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on 12/02/13 at New Delhi by.

**Chief Fire Officer Delhi Fire Service** 

Copy to: -

- 1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1<sup>st</sup> floor, New Delhi w.r.t. letter No.55238/Addl.C.P./Lic(H) dated 18-09-2012.
- 2. The Manager, Taj & Brothers guest house 750, Motor Market, Jama Masjid, Delhi-6.

## Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

## **INSPECTION REPORT**

			D			
1	1. Name & address of the building: Ms Taj & Brothers Quest house, 750, Molor Market,					
2	1. Name & address of the building: Ms Taj & Brothers Guest house, 750, Molor Market, 2. Type of Occupancy: Lodging House Jama masgird, Deller-6					
	3. Type of Case : Renewal / New case					
4	4. Details of previous NOC : Letter No. F6 DF3 [M5 6H 2009 353] Dated: 31 12 2009					
5	5. Fire Safety directives letter No :					
6	6. Date of inspection : 04-02-2013					
7	7. Name of the Inspecting Officers: M.k. Chattopadhyay, Abo (cc)					
8	Name and designation of officers		4			
	from the building side : A	boul Karim	Manager			
	Year of Construction :		V			
10	O. Applicant's letter No. :	238/Addl.C.P/	4°C(H) dale 181	9/2012		
<b>S.</b>	Minimum Standards on fire	NBC	Provided at site	Remarks		
No.	prevention and fire safety U/R 33	Requirement		MR/NMR		
1	Access to building					
	Road width	spl'area	18m+	MR		
	• Gate width	domás .	Directly accomble	MR		
	Width of internal road	MA	74	MA		
2						
	a. Number of staircases	_				
	• Upper Floors	02	02.	MR		
	• Basements	74	r9 A	MA		
	b. Width of staircases		na-	· ·		
	• Upper Floors	0.80 mt	1.06mt, 0.82mh	MR		
	<ul> <li>Basements</li> </ul>	MA	Ma	77		
	c. Protection of exits	N/A	N/A			
	• Fire check door	N/A	N/A			
	<ul> <li>Pressurization</li> </ul>	N/A	N/A			
	e. No. of continuous staircases to terrace	02	02	MR		
	g. Width of Corridor	N/A	N/A			
	h. Door Size	N/A	N/A			
		N/A	N/A			
3	Compartmentation.					

1

	Fire check door	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A		
	• Fire Rating of shaft door	N/A	N/A		
	Water Curtain	N/A	N/A		
	• Fire Dampers	N/A	N/A		
4	Smoke Management System.				
	<ul><li>Basements</li><li>Upper floors</li></ul>	30 a/c per hour 12 a/c per hour	MA	Ma	
			N/A	N/A	
5	Fire Extinguishers	-, «v	8		
	• Total numbers	07,	Provided	MR	
	• Types	ABC, CO2, BC	Provided	MR	
	IS marking	ISI marked	Provided	MR	
6	First-Aid Hose Reels.	*	-		
	• Total numbers on each floor	01	Provided	MR	
	• Length of hose reel hose	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7 Automatic fire detection and alarming system.					
	Type of detectors	N/A	N/A		
	Location of Main Panel	N/A	N/A		
	Location of Repeater Panel	N/A	N/A		
	Alternate source of power	N/A	N/A		
- 10	Hooters' Location	N/A	N/A		
8	MOEFA	MA	N) 4	Mar	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.		8		
	• Basement	N/A	N/A		
	• Upper Floor	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A		
1	Internal Hydrants		-		
	• Size of riser/down-comer	N/A	N/A		
	• Number of hydrants per floor	N/A	N/A		



*	Hose Box	N/A	27/4	
1:	,	IN/A	N/A	
1.	- 12 diants.			
	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	N/A	N/A	
13		N/A	N/A	
	Pumping Arrangements.  • Ground Level			
		N/A	N/A	
	Discharge of main Pump	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	
	Number of main pumps	N/A	N/A	
	Jockey Pump out put	N/A	N/A	
	Jockey pump head	N/A	N/A	
	Standby Pump out put	N/A	N/A	
	Standby Pump Head	N/A	N/A	
=	Auto Starting/ Manual	N/A	N/A	.*
	stopping	N/A		
	Pump House Access		N/A	
	Terrace level	N/A	N/A	
	Discharge of pump	232 LPW	provides	MR
	Head of the pump	30 mf	posndes	Me
	Power Supply  Auto Starting of nump	_	poorided	MR
1.4	Tato Starting of pump	-	Starting switch by near freception	MR Cone
14 Captive Water Storage for fire fighting.				
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A	
	➤ Draw-off connection	N/A	N/A	
	Fire service inlet	N/A	N/A	
	Access to tank	N/A	N/A	
	Overhead Tank capacity	250014	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			TYTE
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/A	N/A	
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	
	Communication In lift Car	N/A	N/A	



	<ul><li>Fireman's Grounding Switch</li><li>Lift Signage</li></ul>	N/A N/A	N/A N/A	
17	Standby power supply	Required	6 KVA	MR
18	Refuge Area.		2	
	Total Area	N/A	N/A	y
	> Location	N/A	N/A	
19	Fire Control Room			
	Detector System Panel	N/A	N/A	
	<ul> <li>Flow Switch Panel</li> </ul>	N/A	N/A	
	<ul> <li>PA System Panel</li> </ul>	N/A	N/A	
	Batter backup	N/A	N/A	
-	<ul> <li>Building Floor Plans</li> </ul>	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	One CQ lyke ties extensionship possible near ( Elect . pane	Me

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to /grant / renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Do(co) forwarded pl.

Do(co) forwarded pl.

Do(co) forwarded pl.

Signature of the Inspecting Officer Name M.K. CHATTOPADHYAY Designation: - Asstt. Div. Officer (CC)