## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI – 11.0001

No: F 6/DFS/MS/2013/ school/115

Dated: 25/05/13

## FIRE SAFETY CERTIFICATE

THE OTHER POLITIFICATE
Certified that the MCD Phimary Boys Girls Cohol, B-1 J-J. Colony Boward Delhi comprised of 12 Mts formal Cabin at Grand floor only owned/occupied by MCD was Boys Girls School Complied with the fire prevention and fire safety requirement in accordance with Director of Education circular Dated:-01/03/2011 and verified by the officer concerned of Fire Service on 7/3/13 in the presence of Lamesh Charder and that the building/premises is fit for occupancy Column building with effect from 25/05/13 for a period of Melegent in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.
Issued on 25/03/13 at New Delhi.

Copy to:-

1 The Kincipal
Mc D Ro. Beys/41 sls school
B-1 J Colony Bowona Lein

My

Chief Fire Officer

Delhi Fire Service

2 The Addl Disector (Edu.) North MCD Civic Curre Minto Rol N. Dum

Note:-This fire safety certificate is subject to compliance of the condition printed over leaf.

1. All the means of escape shall be kept free of all type of obstruction all the time

2. All the employees shall be acquainted with the use and maintenance of a fire equipments and method of smooth and speedy safe evacuation of occupants in case of

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non - functional of fire safety measures, management

4. Any deviation, with regards to construction, electric installation etc. may be got verified from the concerned authorities.

5. Basement shall be used as per BBL.

6. This NOC may not be treated in any case for regularizations of unauthorized.

	INSPECTION	ON REPORT		12					
1.	Name & address of the building MCD Pr	mary B/G	School, B-1,	J.J. Colo	ny				
2.	Name & address of the building MCD Primary B/G School, B-1, J. J. Colo 2. Type of Occupancy Educational Bawana, Do								
3.	N. G. (P								
4.			Dated						
5.	Fire Safety directives letter No Circul	ar, Dir.c	of golin.)	13/11	41				
6.		12013							
7.	2111/1/11								
8.	Name and designation of officers	1 001- 0	logical						
	from the building side	Imesh Ci	TONICA		/				
9.	Year of Construction : 200	5, (12)	No's Poxtor	Capans)					
10	Applicant's letter No.	- dated 1	5-2-2013	3					
	Gu la la Ciara	instalan	Provided at site	Remarks					
S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	I TOTALCA AL SILC	MR/NMR	a <sub>6</sub>				
1		1/3/2011							
	Access to building	1 20: 61.	/ w	MIR					
	Road width	Accessou	6 11	1110					
	• Gate width	-h-	3.64 M	2018					
	Width of internal road	h	open granno	msR					
2	Number, Width, Type & Arrangement of Exits								
	a. Number of staircases	9			_				
	Upper Floors	II.		W y	_				
	• Basements	50) 24							
	b. Width of staircases								
	Upper Floors								
	• Basements								
	c. Protection of exits								
	Fire check door								
	Pressurization		3						
	e. No. of continuous staircases to terrace				х.				
	g. Width of Corridor			0 10					
	h. Door Size	1 m	1 m withdoor	titing M					
3	Compartmentation.		enclor - 4	12 NOS Less	stnanus Stuck				
	Fire check door		MIR						
	<ul> <li>Sealing of electrical shafts</li> </ul>								
	Fire Rating of shaft door								
	Water Curtain								
	Fire Dampers			9	and the control of th				
4	Smoke Management System.				an angelenan				
	Basements	30 a/c per hour	14/6						
	Upper floors	12 a/c per hour							

5	Fire Extinguishers						
	Total numbers	03	Provided	mik			
	<ul> <li>Types</li> </ul>	ABC/Co2 ISI marked	Provided	MIR			
	• IS marking	(29)	provided	" m/L			
6	First-Aid Hose Reels.	440					
	Total numbers on each floor	,	MIK				
	Length of hose reel hose	30 m					
	Nozzle diameter	5 mm					
7	Automatic fire detection and alarming system.						
	Type of detectors	2	MIR				
	Location of Main Panel						
	Location of Repeater Panel						
	Alternate source of power						
	Hooters' Location						
0			NIR				
8	MOEFA	, v .	2/1/				
9	Public Address System.		MIK				
10	Automatic Sprinkler System.		NIR				
	Basement		14/0				
	Upper Floor						
	<ul> <li>Sprinkler above false ceiling</li> </ul>			,			
11	Internal Hydrants						
	Size of riser/down-comer		NIR				
	Number of hydrants per floor		////	id w			
12	Hose Box  Yard Hydrants.		24				
12	Total number of hydrants		NIL	2.0			
	Hose Box						
13							
13	Ground Level		NIR				
	> Discharge of main Pump		1				
	> Head of Main pump						
	> Number of main pumps						
	> Jockey Pump out put						
	> Jockey pump head	2					
	> Standby Pump out put			Action to a real control of the cont			
	> Standby Pump Head						
	> Auto Starting/ Manual						
	stopping  > Pump House Access	2					
	Terrace level			-			
	Discharge of pump						
	Head of the pump	-					
	<ul><li>Power.Supply</li><li>Auto Starting of pump</li></ul>						
	Auto Starting of pump						

	Captive Water Storage for fire fightin			•		
<b>y</b> _		g.				
1	Underground tank capacity		MK			
	> Draw-off connection		1			
	> Fire service inlet			1		
	Access to tank					
	Overhead Tank capacity	,		81		
15	Exit Signage.		NIR			
16	Provision of Lifts.		7 1 7 7 .			
	Pressurization of Lift Shaft		TMA			
	Pressurization of Lift lobby			2		
	Communication In lift Car					
	Fireman's Grounding Switch					
	• Lift Signage					
17	Standby power supply		1			
18	Refuge Area.		NIR			
10						
	> Total Area		MA			
	> Location					
19	Fire Control Room					
	Detector System Panel		NIR	V		
	Flow Switch Panel					
	<ul> <li>PA System Panel</li> </ul>					
	Batter backup					
	Building Floor Plans					
20	Special Fire Protection Systems for					
20	Protection of special Risks, if any:	, S.	NIL			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers..........

Signature of the Inspecting Officer

Signature of the Inspecting Officer 9/3/2013

Name

Name (SHYAM LAL)

Designation Assitt. Dirn. officer

Designation