GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/school/2013/287

Dated: 10/05/13

FIRE SAFETY CERTIFICATE

Certified that Lions Vidhya Mandir Secondary School located at Kushak Lane, New Delhi comprised of ground +two upper floors having total 22 class rooms, one hall & one library owned/occupied by Lions Club of Delhi (Vidya Mandir) Trust was inspected by the officer concerned of this department on 28.04.2013 in presence of Mr.Pradeep Kumar (Principal) and found that the Lions Club of Delhi (Vidya Mandir) Trust have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class Educational (School) with effect from 10/05/13 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules,2010.

Issued on 10/01/13 at New Delhi by.

(Dr. G.C. Misra)

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Tel:- 011-23414333

E-Mail:- cfohq.dlfire@nic.in

Copy to: -

9c P915/13

- 1. The Principle, Lions Vidhya Mandir Secondary School, Kushak Lane, New Delhi
- 2. The Director of Education, Old Secretariat, Delhi

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Lion's Vidya Mandir Secondary School, Kushak Lane, New

Delhi-1

2. Type of Occupancy

: Educational

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/2007/2095 dated 31.07.2007

5. Fire Safety directives letter No : F.16/ESTATE/CC/Fire Safety/2011/3298-3398 dated 01.03.2011

6. Date of inspection

: 28.04.2013

7. Name of the Inspecting Officers : M.K. Chattopadhyay, ADO (HQ)

8. Name and designation of officers

from the building side

: Shri Pradeep Kumar, Principal

9. Year of Construction

: 1960

10. Applicant's letter No.

: nil dated 29-04-2013

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	1 Access to building					
	Road width	06 mts	11 mts	MR		
	Gate width	_	3.0 mts	MR		
	Width of internal road	N/A	N/A	N/A		
2 Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	*	_ < -	-		
	• Upper Floors	04	5 stair + 01 ramp	MR		
	Basements	N/A	N/A	N/A		
	b. Width of staircases	-	-	-		
	• Upper Floors	1.5 mts	1.60(2), 1.20 (2), 1.08(1), Ramp- 1.22 mts	MR		
	Basements	N/A	N/A	N/A		
	c. Protection of exits	DT/A	27/4	27/		
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	N/A	N/A	N/A		
	g. Width of Corridor	02	01 stair + 01 ramp	MR		
		N/A	N/A	N/A		
	h. Door Size	N/A	N/A	N/A		
3	Compartmentation.		Not required			

	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System. Low-rise bldg, Not required					
	Basements	30 a/c per hour	N/A	N/A		
	Upper floors	12 a/c per hour				
			N/A	N/A		
5	Fire Extinguishers					
	Total numbers	12	Provided	MR		
	• Types	ABC, CO ₂	Provided	MR		
-	IS marking	ISI marked	Provided	MR		
5	First-Aid Hose Reels			0		
	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system. Not required					
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
	MOEFA	Required	Provided	MR		
	Public Address System.	N/A	N/A	N/A		
0	Automatic Sprinkler System					
	• Basement	N/A	N/A	N/A		
	Upper Floor Sprinkless days C. Landill	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
1	Internal Hydrants		. 288	TOXI DIS		
	Size of riser/down-comer	100 mm	Provided	MR		

		1				
	Number of hydrants per floor	01	Provided	MR		
,	Hose Box	Required	Provided	MR		
12	Yard Hydrants.					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements					
	Ground Level	N/A	N/A	N/A		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual	N/A	N/A	N/A		
	stopping	N/A	N/A	N/A		
	Pump House AccessTerrace level	N/A	N/A	N/A		
	Discharge of pump	450 LPM (2)	Provided	MR		
	➤ Head of the pump	40 meters	Provided	MR		
	Power Supply	N/A	N/A	N/A		
	> Auto Starting of pump	_	Provided at GF	MR		
14	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	➤ Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	10,000 liters	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.	Not Applicable	*			
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		

	Communication In lift Car	N/A	N/A	N/A
	 Fireman's Grounding Switch 	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
2	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for	Required	01 ABC type fire	MR
	Protection of special Risks, if any:		extinguisher	
			provided	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Note:-The school building is comprised of Ground plus two upper floors each having total 22 class rooms + 01 hall.+ 01 library

7513 *

Dolco on sease

Signature of the Inspecting Officer Name (M.K. CHATTOPADHYAY)

Designation :- Assistant Divisional Officer