## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/School/2013/ 52 / 636

Dated: 29/07/13

## FIRE SAFETY CERTIFICATE

Certified that the **Vidya Memorial Public School** located at G-1/450, Dal Mill Road, Uttam Nagar, New Delhi-110059 comprised of Ground floor plus three upper floors, having total 32 rooms (Including Class Rooms, Offices, Sci. Lab, Comp. Lab & Store etc.) was issued NOC by this department vide letter No.F.6/MS/DFS/2006/1414 dated 28.06.2006 for ground floor plus one upper floor. The School building was reinspected by the officer concerned of this department on 02.07.2013 in the presence of Mr. R.K. Tyagi (Manager) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on  $\frac{2}{3}$  /  $\frac{3}{3}$  at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

 The Manager, Vidya Memorial Public School, G-1/450, Dal Mill Road, Uttam Nagar, N.D-59.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110 054. Following fire safety directives must be adhered to -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

Name 8 and I	CTION REPORT				
Z Type of Occupan	Vidya Memo	nel Rolls et	1 0 1/		
Type of Case	Educational	Whom Alla	1, 67-1/450 Pal mill		
4. Details of Previous NOC	CTION REPORT  Vidya Memorial Public School, G-1/450 Pal Mills  Educational Wham Nagar, New Delli-				
5 Fire Safety dim	Letter No. Folk	Letter No Gilmal a L			
5. Fire Safety directives letter No b. Date of inspection	02 07 2013				
Name of the					
Name of Inspecting Officer	The second secon				
8. Name and designation of officer	s	leep Duggal.			
ule Dullding side	Mr R. K. T.				
9. Year of Construction	2004	2004 (Manager)			
10. Applicant's letter No.	A LA . A B				
Minimum Standards on fire	NBC	WII.	22 05 13		
Prevention and fire safety II/P 33	Requirement	Provided at	Remarks		
Access to building	redamement	site	MR/NMR		
<ul> <li>Road width</li> </ul>					
<ul> <li>Gate width</li> </ul>	Accepible	9m	MR		
* Width of internal road		5m, 3.2m 4 31			
Number, Width, Type & Arrangement		7 2 11 4 51	M MR		
a Number of staircases	of Exits	A part of the second			
* Upper Floors	Two				
* Basements	-dr	Two	MR		
b. Width of staircases		-do-	MR		
* Upper Floor		The second secon	No Basement		
<ul> <li>Basements</li> <li>Protection of exits</li> </ul>		115cms to 1.5 m f	MR Cold cas		
stection of exits			No Basement.		
• Fire check door					
* pressurization			The second secon		
d. No. of continuous staircases to			Secretary and the secretary of the secretary and		
, an ace			-		
e. Width of Corridor		Two			
f. Door Size		140 to 145 cm			
Compartmentation		113 cms			
<ul> <li>Fire check door</li> </ul>			The second secon		
<ul> <li>Sealing of electrical shafts</li> </ul>		· ·			
• Fire Rating of shaft door		The second secon			
* Water Curtain					
• Fire Dampers					
Smoke Management System					
* Basements			And the second section of the section o		
• Upper floors	30 a/c per	The state of the s			
	hour	- 1	to Balement		
	a) months	Valural Ventilation	The second secon		

111 12 a/c per hour Fire Extinguishers Total numbers 10 NoB brovided MR Types ABC 4 co2 -10 MR IS marking ISI marked 1SI Marked MR First-Aid Hose Reels Total numbers on each floor one Provided MR Length of hose reel hose 30 m \_ -do-MR Nozzle diameter 5 mm - do Automatic fire detection and alarming system MR Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 8. MOEFA Public Address System 9 Provided MR Automatic Sprinkler System 10. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants 11. Size of riser/down-comer 100 MM Number of hydrants per floor One Hose Box one 12 Yard Hydrants Total number of hydrants Hose Box **Pumping Arrangements** 13. Ground Level Discharge of main Pump > Head of Main pump > Number of main pumps > Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/Manual stopping

Vidya Memorial Public School, G-1/450, Dal Mill Road ultam Nagar, ND-59.

	Pump House Access			-			
	<ul> <li>Terrace level</li> </ul>		9 1				
	Discharge of pump	450 Um	ysoulm	MR			
	Head of the pump	30m	30 m	me			
	Power Supply	Required	frovided	MR			
	Auto Starting of pump		No -				
14.	Captive Water Storage for fire fighting						
	<ul> <li>Underground tank capacity</li> </ul>						
	Draw-off connection	-					
	Fire service inlet	-					
	Access to tank			-			
	Overhead Tank capacity	10,000 ly	Provided	MR			
15.	Exit Signage.	Required	-do	MR			
16.	Provision of Lifts.						
	Pressurization of Lift Shaft		- (No Lift)	No lift			
	<ul> <li>Pressurization of Lift lobby</li> </ul>			0			
	Communication In lift Car						
	<ul> <li>Fireman's Grounding Switch</li> </ul>						
	Lift Signage						
17.	Standby power supply						
18.	Refuge Area.						
**************************************	> Total Area	-					
	Location						
				5			
19.	Fire Control Roam						
	<ul> <li>Detector System Panel</li> </ul>						
	<ul> <li>Flow Switch Panel</li> </ul>						
	<ul> <li>PA System Panel</li> </ul>		-				
	Batter backup		· ·				
	<ul> <li>Building Floor Plans</li> </ul>						
20.	Special Fire Protection System for Protection of special Risks, if any:						

1/6

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers

Note: The school building is Comported of Ground plus three upper floors having rooms. Previously NOC provided to same building was for ground plus one floor only. Now two more upper floors are constructed and fire safety arrangements for the premises has been provided as per NBC. Declaration togs. Students less than 45 in each is endosed letter no nil deted 15.07.2013.

Signature of Inspecting Officer

Name SANDEEP DUGGAL

Designation ASSA - Divisional Officer.

Signature of Inspecting Officer

Name

Designation

Date 22 TB Diary No 658