## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/EH/2013/ 7/2

Dated: 14/8/13

## **FIRE SAFETY CERTIFICATE**

Certified that the M/S Pind Balluchi-Grills & Platters (A unit of IKO Hospitality Pvt. Ltd.) located at R-1, S-1, S-2, West end convention point, Plot No. 15, 16, District Centre, Janakpuri, New Delhi. The building comprised of Basement, ground floor plus three upper floors. The restaurant is running at Ground floor only of above said building. The restaurant having three exits owned/occupied by IKO Hospitality Pvt. Ltd. The Restaurant was inspected by the officer concerned of this department on 31.07.2013 in the presence of Sh. N.N. Mishra (Project Manager) and found that the management of restaurant have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class Group D assembly building Sub- Division D-6 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 19/8/2013 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

 The Dy. Health Officer (West Zone), South Delhi Municipal Corporation, Public Health Department, West Zone, Rajouri Garden, New Delhi-110024. (Ref. No. D/3006 HD/WZ/2013 dated 19.06.2013) ble Ony

 Sh. Parminder Singh, M/S Pind Balluchi-Grills & Platters, R-1, S-1, S-2, West end convention point, Plot No. 15, 16, District Centre, Janakpuri, New Delhi Following fire safety directives must be adhered to -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

Note: The restaurant running at graund flourant

	1 Name 8 - LL - 5	TION REPORT	4.4				
	1. Name & address of the building:	m/s find Balluchi-	- Grailla & Platters	et R-1, S-1, S-2			
	z. Type of Occupancy	Assembly.	West end Conker	nion foint, plot 15,16			
	3. Type of Case	: New Case/Renev	val	diffich and Videna			
	4. Details of Previous NOC  5. Fire Safety directives letter No.	: Letter No		Date —			
	a social directives letter 140						
	6. Date of inspection	31/07/2013					
	7. Name of Inspecting Officer	A.DO. Sandee	b Duggal.				
	o. Name and designation of officers						
	From the building side	: Mr N. W. Mishig	(Project Manager)				
	9. Year of Construction	2007					
S.	10. Applicant's letter No.	D/3006/HD/WZ/	2013 dated 190	6 2013			
	Minimum Standards on fire	NBC	Provided at	Remarks			
No.	prevention and fire safety U/R 33	Requirement	site	MR/NMR			
1.	Access to building						
	Road width	Accessible	12 m	MR			
	Gate width		182 ,220,110 cmg				
	<ul> <li>Width of internal road</li> </ul>		102 122 , no emg	MR			
2.	Number, Width, Type & Arrangemen	t of Exits					
	a. Number of staircases						
	• Upper Floors			0.1. (10. 10.			
	<ul> <li>Basements</li> </ul>			Restaurant at Ground flo			
	b. Width of staircases			_do_ 0			
	Upper Floor			Restaurant sunning out			
	Basements			Ground floor only			
	c. Protection of exits			-do-01			
	Fire check door						
	• pressurization	0					
	d. Not of continuous staircases to		<b>.</b>				
	terrace	March and Control of the Control of					
	e. Width of Corridor			-			
	f. Door Size	-					
	1.   5001 3126		182,220,110 cms	MR			
3.	Compartmentation		102/20/110 012	1			
-							
	Fire check door						
	<ul> <li>Sealing of electrical shafts</li> </ul>						
-	<ul> <li>Fire Rating of shaft door</li> </ul>						
	Water Curtain						
	<ul> <li>Fire Dampers</li> </ul>						
4.	Smoke Management System						
	Basements	30 a/c per					
	Upper floors	hour	Natural Ventilation				
	The state of the s	-	and the second	MR			

	N/2	n-village n-village n-village	, d			
		12 a/c per hour ~	_			
5.	Fire Extinguishers					
	<ul> <li>Total numbers</li> </ul>	06	Provided	MR		
	• Types	ABC,CO2	-do,-	MR		
. !	<ul> <li>IS marking</li> </ul>	ISI marked	151 marked	MR		
6.	First-Aid Hose Reels					
	<ul> <li>Total numbers on each floor</li> </ul>	one	Provided	MR.		
v.	<ul> <li>Length of hose reel hose</li> </ul>	30 m	- do	MR		
7	Nozzle diameter	5 mm	-do-	MR		
7.	Automatic fire detection and alarming system					
i	Type of detectors	smoke 4 heat dele	ely Provided	MR		
	Location of Main Panel	-				
	<ul> <li>Location of Repeater Panel</li> </ul>					
E 2	Alternate source of power	Required	DG Set of 125 KYA	MR		
8.	Hooters' Location					
9.	MOEFA	Required	Poovided	MR		
10.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System			0.00		
	Basement Grund Ppper Floor	^		Restaurant of GF		
	• Sprinkler above false ceiling	Required	Provided	MR		
11.	Internal Hydrants					
	Size of riser/down-comer	to a new	100			
	• Number of hydrants per floor	100 mm	100 mm	MR		
	Hose Box	one	pne	MR		
12.	Yard Hydrants	one	one	MR		
	<ul> <li>Total number of hydrants</li> </ul>		J.			
	<ul> <li>Hose Box</li> </ul>					
13.	Pumping Arrangements					
	<ul> <li>Ground Level</li> </ul>		*			
	Discharge of main Pump	900 Lpm	2280 LPM	MR		
	Head of Main pump	30 mts	Somtr	MR		
	Number of main pumps	-	2280 LPM XT			
	> Jockey Pump out put		630 Um	MR		
	<ul><li>Jockey pump head</li><li>Standby Pump out put</li></ul>		80 mtr	MR		
	<ul><li>Standby Pump out put</li><li>Standby Pump Head</li></ul>		2280 Um	MR		
İ	> Auto Starting/Manual		80 m	MR		
	stopping			T'I'		
	2.0556		/-	Talink V		
		and the second		The fire pumps are		

Common for the building.

	Pump House Access						
	<ul> <li>Terrace level</li> </ul>			1			
	Discharge of pump		_				
	Head of the pump		- Constitution of the Cons				
	Power Supply						
	Auto Starting of pump		-	sovided at baser			
			(hs	sovided at Baser			
14.	Captive Water Storage for fire fighting						
	<ul> <li>Underground tank capacity</li> </ul>		50,000 Lm	MR			
	Draw-off connection		provided	MR			
1	Fire service inlet		Provided	MR			
	Access to tank		provided	MK			
	<ul> <li>Overhead Tank capacity</li> </ul>	15000	25000	MR			
15.	Exit Signage.	Required	Provided	MR			
1.0	Provision of Lifts.						
16.	Pressurization of Lift Shaft						
	Pressurization of Lift lobby						
	Communication In lift Car						
	• * Fireman's Grounding Switch						
	Lift Signage	-					
17.	Standby power supply	Required	DG set of 125 km	MR			
18.	Refuge Area.						
10.	> Total Area						
	> Location						
19.	Fire Control Room						
	<ul> <li>Detector System Panel</li> </ul>	-	pa-				
	<ul> <li>Flow Switch Panel</li> </ul>						
	PA System Panel						
	Batter backup						
	Building Floor Plans						
	- Bananig Hoor Hains						
1		1		4			
20.	Special Fire Protection System for Protection of special Risks, if any:			-			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Note: The restaurant is running at graund floor of a building comprised of basement, ground floor plus three upper floors. The restaurant area having three exits. and kitchen having two exits. Hose red, hydrank with hose box, sprinkler, heat I smoke detector, fire Entinguishers, MOEFA, PASystem, Emergency light 4 exit signs at are provided in the restaurant area. FSC is recommended for restaurant sunning at ground floor only.

Signature of Inspecting Office 12613

Name Sandeep Duggal

Designation Asst. Divisional OfficeV.

Signature of Inspecting Officer

Name

Designation

FIRE SEAL