GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001 Fax: 23412593, Email: director.dlfire@nic.in Tel: - 01-23414000

NO. F6/DFS/MS/GH/2013/ 102/1030

Dated: 04//0//3

FIRE SAFETY CERTIFICATE

Certified that Muskan Lodge, 1367-Punjabi Phatak, Ballimaran, Delhi-6, comprised of ground (Commercial), first floor (01 hall for 05 beds), Second floor (01 hall for 05 beds) and terrace (Open area) Total 02 halls for 10 beds, was granted NOC by this department vide letter No. F.6/MS/DFS/GH/09/1770 dated 16-06-2009. The premises was re-inspected by the officer concerned of this department on 25-09-2013 in the presence of Sh. Feroz Ahmad, Owner of the guest house and found that the said guest house is located in special area have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy of 02 halls for 05 beds each with effect from or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on $\frac{\alpha 4/(\sigma //3)}{2}$ at New Delhi by.

(A.K. SHARMA) DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

2. M/s Muskan Lodge, 1367-Punjabi Phatak, Ballimaran, Delhi-6,

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time.
- b. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- c. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- d. The trained fire fighting staff shall be available round the clock.
- e. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1.	Name & address of the building	 Muskan	Lodge	1367	Punjabi	Phatak
		Ballin	maran	Delh	ù-6	

2. Type of Occupancy : Lodging-

3. Type of Case : Renewal

4. Details of previous NOC : Letter No F.6/MS/DFS/GH/09/1770 Dated 16/05/09

5. Fire Safety directives Letter No. H. M.L.

6. Date of inspection : 25-09-2013

7. Name of the Inspecting Officer: Sanjay Tomar, Do

8. Name and designation of Officer from the building side Sh. Feroz Ahmad.

9. Year of Construction Started in 2009

10. Applicant's letter No.: -- HL clated 16-09-2013

S No	Minimum standards on fire prevention and fire safety U/R 33		Provided at site	Remarks MR/NMR old case
	Access of building			
	Road width	opx area	hocated in appropriate of the state of the s	ME COLUMN
	Gate width	T/A	Smirs from motor	H/A .
	Width of internal road	HIA	HIA	N/A
	Number, width, Type & Arrangeme	ents of exits	-	
	a. Number of staircases			
	•	One	one	MR
	Upper floors			
		MA	HIA	N/A
	Basements		and an arrangement and arrangement and arrangement and arrangement and arrangement and arrangement arr	
	b. Width of staircasesUpper floors	80 cms (Spl. Area)	81 to 90 Cms Provided	MR (Splotreo
	Basements	HIA	H/A	TI/A
	c. Protection of exits			
	Fire check door	414	H/A	MIA
	Pressurization	H/A	~/A	HIA
	d. No of continuous staircase to terrace	One	One	Provided
	e. Width Of Corridor	r/A	MA	n)A
	f. Door Size	HIA	H/A	MIA

)		4/4		old cost
1				
0-11	translation			
- Automoran	npartmentation Fire check door			
1	• Fire check door	***	11-11-11	
	Sealing of electrical shafts			
	Scaring of creatives			
	• Fire Rating of shaft door			
			H	
	Water Curtain		A	
			H	
	Fire Dampers			
	1 Cyatam			
Sn	noke managements System	30 a/c per hour		
	 Basements 	22 m 2 h 2	N	
26	II or floors	12 a/c per hour		A
	 Upper floors 			
Fi	re Extinguishers			
11	Total numbers	OH	Provided	MR
	• Types	6. 0 345 0-4	OH nos.	
	IS marking	CO2 & WCO2, ABC	Provided	MR
	TO Illuming	ISI marked		
			Provided	MR
		510 6 05	QUIRED	
5. F	First – Aid Hose Reels			10/0.
	 Total numbers on each floor 	Not required	One Provided	MR/Acceptat
			Provided	Acceptable
	 Length of hose reel hose 	30 mtr	1700000	
	A. I. Hamatar	5mm	Provided	Acreptable
	 Nozzle diameter 	THE RESIDENCE OF THE PARTY OF T	NAME OF TAXABLE PARTY.	
7.	Automatic fire detection and alarm	ing system		
1.	Type of detectors			
	TJPO			
	 Location of Main Panel 			
			+++++++++++++++++++++++++++++++++++++++	
	 Location of Repeater Pane 	1		
	 Alternate source of power 	× 1	11/	
			0	
	Hooters' Location		A	
-	MODEA			
8.	MOEFA			
-	Public Address System			
9.	rubiic Address bystom			
1	Automatic Sprinkler System			
10	Automatic philities of acc		N	
10.	Dagamente	1		The state of the s
10.	Basements			0
10.	BasementsUpper Floor			A

old cost

Ti .				
	 Sprinkler above false ceiling 			a grand and a second
11.	Internal Hydrants			
1,1.			T	
	Size of riser/down- comer			
				*
	Number of hydrants per			
	floor			**
	1001			
	Hose Box			8
12.	Yard Hydrants			
12.				
	Total number of hydrants		a 2 x	
	Hose Box			
13.	Pumping Arrangements	The state of the s	**************************************	
13.	1 uniping Arrangements			
	Ground Level			
	Discharge of main pump			
	➤ Head of main pump			
	➤ Head of main pump			
	Number of main pumps			
	> Jockey pump out put			
		1.1. 2 1.1. 2 1.1. 2		
	Jockey pump head		/ /	
2	G 41 D			
	➤ Standby Pump out put	1		
	Standby Pump Head			
	A (4.4			
	> Auto Staring/Manual			
1	stopping			
1		100/01/01/01/01/01		
	➤ Pump House Access	/ . rs . r .		
	, I unit i i uso i recess			
	Terrace level			
	> Discharge of pump		225 LPM	
	/ Discharge of pump	Hot-Required	Provided	Acreptably
		100	1.0.000	1 1000
	> Head of the pump	11 D 1	30 meter	Accetable
		Hot Required	Provided	mendoe.
	> Power supply			
	y 1000 suppriy	Not Required	Provided	Accetable
	➤ · Auto starting of pump	Not Required	Switch Provided	Acceptable
14.	Captive water Storage for fire fighting	g		
	. • Under ground tank capacity			
	> Draw of connection			and the second s
	Fire service inlet			
	Access to tank			
		1.10		
	Overhead Tank capacity	Not Required	2500 limes	Acceptable
			Provided	
15	Exit Signage	0	0	
		Require of	Provided	MR
L				

· Muskanhodge, 1367, Punjabi Phatak, Balli maran, Delli-6

	A AU TADIUM VA MILIEU	GLN		
	Pressurization of Lift Shaft			old cost
2	➤ Pressurization of lift lobby			
	> Communication in lift Car		N	
	Fireman's Grounding Switch		A	
	Lift Signage			
7.	Standby power supply	Required	Emergency higher Provided	TR
8.	Refuge Area			
	> Total area		7/	
	> Location		A	
19.	Fire control room			
	> Detector system panel			
	> Flow Switch Panel			
	> PA System Panel		H	
	> Batter backup		A	
	Building Floor Plans			
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Required	Provided near Ele	ar mR

the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial numbers

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name

Name Sanjay Kumar Tomar

Designation Divisional Officer

Designation