GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. FE DES MS School 2013 W2 1289

Dated: 06 / 12/2013

FIRE SAFETY CERTIFICATE

Certified that the New Bal Bharti Sec. School. Pocket-7, Sector-2, Rohini-85 comprised of Basement + Ground + Two upper floor owned/occupied by New Bal Bharti Sec. School have complied with the fire prevention and fire safety requirements in accordance with the Circular No F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education / NBC- Part IV and verified by the officer concerned of Fire Service on 21/10/2013 in the presence of Sh. Sandeep Dahiya and that the building / premises is fit for occupancy of Educational building with effect from 66 / 12/2013 for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1 All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2 Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3 The trained fire fighting staff should be available round the clock.
- 4 Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5 The basement shall be used strictly as per the provision of building bye laws.
- 6 This certificate cannot be treated in any case for regularizations of unauthorized construction
- 7 The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on 06.12.2013 at New Delhi

(SANTOKH SINGH) Chief Fire Officer Delhi Fire Service Ph: 011-23414250 cfowz.dlfire@nic.in

8ca

Copy to:

- 1. The Principal, New Bal Bharti Sec. School. Pocket-7, Sector-2, Rohini-85
- 2. The Director of Education, Old Secretariat, Delhi

INSPECTION REPORT

1. Name & address of the building: New Bal Bharti Sec. School. Pocket-7, Sector-2, Rohini-85

2. Type of Occupancy

: Education (B+G+2)

3. Type of Case

: New

4. Details of previous NOC

: Nil

5. Fire Safety directives letter No : NBC Part IV

6. Date of inspection

: 21/10/2013

7. Name of the Inspecting Officers: DO(NW)

8. Name and designation of officers

from the building side

: Sh. Sandeep Dahiya

9. Year of Construction

: 2006

10. Applicant's letter No.

: NBBPS/13/20133315

dated 10/09/2013

PA-900 Sa.m.

CA-650 sq vards

NOS-425

NOT-17

CD 16

	PA-900 Sq.m. CA-650 sq yards	NOS-425	NOT-17 CR-16			
	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	Accessible	Accessible	M/R		
	Gate width					
	Width of internal road					
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		8 2 2 2			
	Upper Floors	02	02	M/R		
	Basements	01	P	M/R		
	b. Width of staircases					
	• Upper Floors	1.5 mtr	1) 1.5 mtr Pucca 2) Iron S/case 1.5 mtr.	M/R		
	Basements	1.5 mtr	1.5 mtr	M/R		
	c. Protection of exits					
	Fire check door	N/A	N/A	N/A		
	 Pressurization 			HOC \$17000H4 (6000)		
	e. No. of continuous staircases to terrace	· N/A	N/A	N/A		
	g. Width of Corridor					
			1.8 mtr			
	h. Door Size	1 mtr	1.1 mtr	M/R		

3	Compartmentation.	,		ž.		
	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
	• Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
	Basements	30 a/c per hour	N/A	N/A		
	 Upper floors 	12 a/c per hour	N/A	N/A		
5	Fire Extinguishers					
	Total numbers	10	10	M/R		
	• Types		ABC	M/R		
	IS marking	ISI marked	Yes	M/R		
6	First-Aid Hose Reels.					
	Total numbers on each floor	R	P	M/R		
	• Length of hose reel hose	30 m	P	M/R		
	Nozzle diameter	5 mm	P	M/R		
7	Automatic fire detection and alarming system.					
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	N/A	N/A	N/A		
9	Public Address System.					
10	Automatic Sprinkler System.					
	Basement	R	P	M/R		
	Upper Floor	,	<u></u>			
	Sprinkler above false ceiling					
11	Internal Hydrants					
	Size of riser/down-comer	N/R	N/R	N/R		
	Number of hydrants per floor	N/R	N/R	N/R		
	Hose Box	N/R	N/R	N/R		

12	Yard Hydrants.				
	 Total number of hydrants 	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level			3.	
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stopping	N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	Terrace level				
	Discharge of pump	900 LPM	P	M/R	-
	Head of the pump	40m	P	M/R	-
	Power Supply	R	P	M/R	1
14	 Auto Starting of pump Captive Water Storage for fire fighting 	R	P	M/R	1
		Ş•			
	Underground tank capacity		8 7 1 1		
	Draw-off connection	N/A	N/A	N/A	100
	Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	15,000 ltr	15,000 ltr	M/R	-
15	Exit Signage.	R	Р	M/R	
16	Provision of Lifts.				+
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	 Pressurization of Lift lobby 	· N/A	N/A	N/A	
	• Communication In lift Car	N/A	N/A	N/A	
	• Fireman's Grounding Switch	N/A	N/A	N/A	-
	• Lift Signage	N/A	N/A	N/A	
17	Standby power supply	R	5 KVA	M/R	

4.0				
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room		L	
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Signature of the Inspecting Officer

Designation 3 Ar

Signature of the haspeeting Officer
Jame
Designation

Name

Name

Designation