GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

NO.F6/DFS/MS/EH/2013/ 52 /1311

Dated: 13 | 12 | 13

FIRE SAFETY CERTIFICATE

Certified that Sanghai-30 Restaurant (A unit of Aarm Healthcare Private Limited) located at ground & Mezzanine Floor (seating capacity 96) of E-30, Hauz Khas main market, Hauz Khas, New Delhi-16 was inspected by the officer concerned of this department on 01-12-2013 in presence of Mr. Ashly Alemao, CEO of the restaurant and found that the said restaurant have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and that the premises / building is fit for occupancy class Assembly group-D (restaurant) with effect from 13/12/13 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi fire service Rules, 2010.

Issued on 13/12/13 at New Delhi by.

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to: -

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

2. Deputy Health Officer, South Zone, SDMC, Health Department, Aurbindo Marg, Green Park, New Delhi.

3. The CEO, Sanghai-30 Restaurant (A unit of Aarm Healthcare Private Limited), E-30, Hauz Khas main market, Hauz Khas, New Delhi-16

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building :Sanghai-30 Restaurant (A unit of Aarm Healthcare Private

Limited), E-30, Hauz Khas main market, Hauz Khas, New

Delhi

2. Type of Occupancy

: Restaurant (Assembly group-D)

3. Type of Case

: New Case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No

: Delhi Fire Service Act 2007 & Rules 2010

6. Date of inspection

: 01-12-2013

7. Name of the Inspecting Officers : Atul Garg, DCFO(SZ), M.K.Chattopadhyay, ADO(M.Rd)

8. Name and designation of officers

from the building side

: Mr. Ashly Alemao, CEO

9. Year of Construction

: 1966

10. Applicant's letter No.

: Nil dated 27.09.2013.

Restaurant is located on ground & Mezzanine floor (seating capacity 96) of a building comprised of

basement, ground, mezzanine & three upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirements	Provided at site	Remarks MR/NMR	
1	Access to building		2		
	Road width	0 % mts	Provided	MR	
	• Gate width	4.5 mts	Directly accessible	MR	
	 Width of internal road 	N/A	N/A	N/A	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases	-	_		
	• Upper Floors	02	Provided	MR	
	 Basements 	N/A	N/A	N/A	
	b. Width of staircases	-	-	-	
	Upper Floors	1.25 mts	1.38-1.65 mts & 1.10 mts	MR	
	Basements	N/A	N/A	N/A	
	c. Protection of exits			0	
	Fire check door	Ņ/A	N/A	N/A	
	 Pressurization 	N/A	N/A	N/A	
	e. No. of continuous staircases to terrace	01	01	MR	
	g. Width of Corridor	N/A	N/A	N/A	
	h. Door Size	2.0 mts	2.0 mts, 0.90 mts	MR	
3	Compartmentation.	p			



	Fire check door	N/A	N/A	NA	
	 Sealing of electrical shafts 	N/A	N/A	N/A	
	Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.				
	• Basements	30 a/c per hour	N/A	N/A	
	Upper floors	12 a/c per hour	Provided	MR	
5	Fire Extinguishers				
	Total numbers	16	Provided	MR	
	• Types	ABC, CO ₂	Provided	MR	
	IS marking	ISI marked	Provided	MR	
5	First-Aid Hose Reels.				
	Total numbers on each floor	01	Provided in restaurant	MR	
	 Length of hose reel hose 	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	Not Required	Provided		
	Location of Main Panel	Not Required	Provided		
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	Not Required	Provided		
	Hooters' Location	Not Required	Provided		
3	MOEFA	Required	Provided	MR	
)	Public Address System.	N/A	N/A	N/A	
0	Automatic Sprinkler System.	1771	IVA	1071	
	Basement	Not Required	Provided		
	Upper Floor	(area <100 m ²) Required	Provided		
	 Sprinkler above false ceiling 	1,3,100	Tiorided	MR	
		N/A	N/A	N/A	
1	Internal Hydrants				
	Size of riser/down-comer	100 mm	Provided	MR	
	 Number of hydrants per floor 	01	Provided	MR	
	 Hose Box 				
		01	Provided	MR	



12	Yard Hydrants.				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level	-	-	-	
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual	N/A	N/A	N/A	
	stopping	N/A	N/A	N/A	
	➤ Pump House Access	N/A	N/A	N/A	
	Terrace levelDischarge of pump	450 LPM	Provided	MR	
	Head of the pump	40 mts	Provided	MR	
	> Power Supply	Required	Provided	MD	
	➤ Auto Starting of pump	Required	provided	MR MR	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	N/A	N/A	· N/A	
	➤ Draw-off connection	N/A	N/A	N/A	
	Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	10,000 liters	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	



	Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	125 KVA Provided	MR
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	01 CO ₂ type fire extinguishers found provided near elect. panel	MR

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

DFA is put up for approval & signature please.

3/ *

Signature of the inspecting Officer

Name :- Atul Garg

Designation: - Dy. Chief Fire Officer

Signature of the Inspecting Officer Name M.K.CHATTOPADHYAY

Designation: - Asstt. Div. Officer (M.Rd)