FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE. CONNAUGHT PLACE

NEW DELHI

FBIDES MS | EN /2014 | W2 / 327

Dated: 10 3 14

FIRE SAFETY CERTIFICATE

Certified that the McDonalds Family Restaurant by Connaught Plaza Restaurants Pvt. Ltd. located at Anchor No.1, D Mall, Ground Floor, Netaji Subhash Place, Pitampura, Delhi -110034 was issued FSC vide Letter No. F6/DFS/MS/EH/2010/3118 dated 10-11-2010. The D Mall, Netaji Subhash Place has already issued FSC vide letter no. F6/DFS/MS/2012/2059 dated 06-06-2012. The premises was re inspected by the officers concerned of this department on 10-01-2014 in the presence of Mr. D N Thakur (Senior Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect 10/3/19 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules. 2010.

Chief Fire Officer, Delhi Fire Service 901

Copy to:

No.

1. Sh. Harish Sharma (Authorised Signatory). Connaught Plaza Restaurants Pvt. Ltd.. 13A. Jor Bagh Market, New Delhi 110003.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

 Name & address of the building: McDonalds Family Restaurant by Connaught Plaza Restaurants Pvt. Ltd., Anchor No.1, D Mall, Ground Floor, Netaji Subhash Place, Pitampura, Delhi – 110034.

2. Type of Occupancy

: Assembly

3. Type of Case

: Renewal (Situated in Mall already issued NOC vide letter no.

F6/DFS/MS/2012/2059 dated 06-06-2012)

4. Details of previous NOC

: Letter No. F6/DFS/MS/EH/2010/3118 dated 10-11-2010

5. Fire Safety directives Letter No. : FSC Issued to the mall

6. Date of inspection

: 10-01-2014

7. Name of the Inspecting Officer: Mukesh Verma, ADO (MN)

8. Name and designation of Officer

from the building side

: Sh. D N Thakur (Senior Manager)

9. Year of Construction

: 2010

10. Applicant's letter No.

: CPRPL/FM/NOC/2013-14/A25 dated 06-11-2013

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR	
1.	Access of building				
1.	Road width	6 m	30m Provided	MR	
	• Gate width	NA	NA	NA	
	Width of internal road	NA	NA	NA	
2.	Number, width, Type & Arrangements of exits				
	a. Number of staircases			N. A.	
	 Upper floors 	NA	NA	NA	
	• Basements	NA	NA	NA	
	b. Width of staircases				
	 Upper floors 	NA	NA	NA	
	Basements	NA	NA	NA	
	c. Protection of exits				
	• Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA	
	d. No of continuous staircase to terrace	NA	· NA	NA	
	e. Width Of Corridor	NA	NA	NA	
	f. Door Size	Old Case	Old Case	Old Case	
3.	Compartmentation				
-	Fire check door	NA	NA	NA	

	Sealing of electrical shafts	NA	NA	NA			
	 Fire Rating of shaft door 	NA	NIA				
	Water Curtain	NA	NA NA	NA ·			
	• Fire Dampers	NA		NA			
4.	Smoke managements System	17/7	NA	NA			
	Basements	30 a/c per hour	NA	NIA			
	Upper floors	12 a/c per hour	Provided	NA			
	opper moors	12 a/c per nour	Provided	MR			
5.	Fire Extinguishers						
	 Total numbers 	02 nos. each type	Provided	MR			
	 Types 	DCP, CO2 &	Provided	MR			
	IS marking	WCO2	1 To Videa	IVII			
		ISI marked	Provided	MR			
6.	First – Aid Hose Reels			1711			
	 Total numbers on each floor 	1	Provided	MR			
	 Length of hose reel hose 	30 m	Provided	MR			
	 Nozzle diameter 	5 mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	 Type of detectors 	Smoke	Provided	MR			
	 Location of Main Panel 	Required	Provided at GF	MR			
	 Location of Repeater Panel 	NA	NA	NA			
	Alternate source of power	Required	Provided	MR			
	 Hooters' Location 	Required	Provided at	MR			
			entrance				
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	NA	Provided	MR			
10.	Automatic Sprinkler System						
	 Basements 	Not Required	NR	NR			
	 Upper Floor 	Required	Provided	MR			
	 Sprinkler above false ceiling 	Required	Provided	MR			
11.	Internal Hydrants: common with the mall						
	 Size of riser/down- comer 	150 mm	Provided	MR			
	 Number of hydrants per 	1	Provided	MR			
	floor			1			
	Hose Box	Required	Provided	MR			
12.	Yard Hydrants						
	 Total number of hydrants 	NA	NA	NA			
1.0	Hose Box	NA	NA	NA			
13.	Pumping Arrangements: Common with the mall						
	Ground Level						
20	 Discharge of main pump 	NA	4500 lpm	NA			
	Head of main pump	NA	65m	NA			
	Number of main pumps	NA	2	NA			
	Jockey pump out put	NA	180 lpm	NA			
	Jockey pump head	NA	65m	NA			
	Standby Pump out put	NA	4500 lpm	NA			
	Standby Pump Head	NA	65m	NA			
	Auto Staring/Manual	NA	Provided	NA			

	stopping				
	Pump House Access	NA	Provided	NA	
	Terrace level	1 1/1	Trovided		
	Discharge of pump	900 lpm	Provided	MR	
	Head of the pump	40 m	Provided	MR	
	Power supply	Required	Provided	MR	
	Auto starting of pump	Required	Provided	MR	
1.4	Captive water Storage for fire fighting		The state of the s	17110	
14.		NA	2,50,000 litres	MR	
	 Under ground tank capacity Draw off connection 	NA	Provided	MR	
		Required	Provided	MR	
	Fire service inlet	NA	Provided	MR	
	Access to tank		50, 000 Litres	MR	
7,0	 Overhead Tank capacity 	10, 000 litres	Provided	IVIK	
		n ' 1		MR	
15	Exit Signage	Required	Provided	MR	
16.	Provision of Lifts			NIA	
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of lift lobby	NA	NA	NA	
	Communication in lift Car	NA	NA	NA	
	Fireman's Grounding	NA	NA	NA	
	Switch	NA	NA	NA	
	Lift Signage				
17.	Standby power supply	Required	Provided	MR	
18.	Refuge Area				
	Total area	NA	NA	NA	
	Location	NA	NA	NA	
19.	Fire control room				
	Detector system panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Battery backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20.	Special Fire Protection Systems for	NA	NA	NA	
	Protection of special Risks, if any;			g C	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/EH/2010/3118 dated 10-11-2010 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Name

Name Mukesh Verma: 191214. Designation ADD (MN)

Designation