GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F610FS1m12014 | 1102/564

Dated: 2 15 /14

FIRE SAFETY CERTIFICATE

Issued on 21572019 at New Delhi by

(Dr.G.C.Misra) Chief Fire Officer T.No.011-2341333

Copy to:-.

- Principal, Bishop Boys Diocesan School,
 6-B, Rajpur Road, Delhi-54.
- The Addl. Director (Education)
 MCD, Nigam Bhawan,
 Kashmere Gate, Delhi-06.

Conditions for the validity of fire safety certificate are overleaf:-

CONDITIONS:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT : Bishop Boys Diocesan School, 6-B, Rajpur Road, Delhi-54.

1. Name & address of the building

2. Building is comprised of

3. Type of Occupancy 4. Type of Case

5. Details of Previous NOC

6. Fire Safety direction letter No

: Education : Renewal

: 23.04.14.

: Vedpal (ADO)

: G+2

: No:F6/DFS/MS/2011/555, Dated 29.03.2011. : F.16/Estate/CC/Fire safety/2011/3298 to 3398

Dated-01.03.11

7. Date of Inspection

8. Name of the Inspecting Officers:

9. Name and designation of Officer from the building side

10. Year of Construction

11. Applicant's letter No

: Ms.Monica Massey(Principal)

:No.B.B.D.S/14/10, dated 12.3.14

S.No	Minimum Standards on fire		Provided at	Remarks		
	prevention and fire safety as per		Site	MR/NMR		
	circular no.3298-3398 Dated01.03.11					
1	Access to building					
	Road width	6 m	6 m	MR		
	Gate width Width of internal road	N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
2	Number, Width, Type and Arrangement of Exits.					
	a. Number of Staircases	***************************************	*			
	Upper Floor Basement B. Width of Staircases Upper Floor Basement c. Protection of exits Fire check door Pressurization e. No. of continuous staircases to terrace g. Width of Corridor h. Door Size	2nos.	2nos.	MR		
		N.A.	N.A.	N.A.		
			*	10-10-00-00-00-00-00-00-00-00-00-00-00-0		
		1.5 m	1.5&1.4m	MR		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		1no.	1no.	MR		
		1.5 m	1.5 m	MR		
		1 m	1m	MR		
3	Compartmentation					
	Fire check door Sealing of electrical shafts Fire rating of shaft door Water curtain Fire Dampers	N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
		N.A.	N.A.	N.A.		
1		N.A.	N.A.	N.A.		
4	,	N.A.	N.A.	N.A.		
l I	Smoke Management System.					
	Basement	30a/c per hour	N.A.	N.A.		
	Upper floor	12 a/c per hour	N.A.	N.A.		

N18

Bishop Boys Diocesan School, 6-B, Rajpur Road, Delhi-54.

	Fire Extinguisher Total numbers 06nos 06 nos MP						
	types		06 nos.	MR			
	IS marking	CO ₂ & ABC	ABC Type	MR			
3	First-aid-Hose Reels.	ISI marked	ISI marked	MR			
	Total numbers of each floor	01no.					
	Length of hose reel hose		01no.	MR.			
	Nozzle diameter	30m	30m	MR.			
7		5mm	5mm	MR.			
-	Automatic fire detection and alarming system. Type of detectors N.A.						
	Location of main panel Location of repeater panel Alternate source of power Hooters	N.A.	N.A.	N.A.			
		N.A.	N.A.	N.A.			
		N.A.	N.A.	N.A.			
		N.A.	N.A.	N.A.			
		N.A.	N.A.	N.A.			
3	MOEFA	N.A.	N.A.	N.A.			
9	Public address System.	N.A.	N.A.	N.A.			
10	Automatic Sprinkler System.						
	Basement	N.A.	N.A.	N.A.			
	upper floor	N.A.	N.A.	N.A.			
	sprinkler above false ceiling	N.A.	N.A.	N.A.			
11	Internal Hydrants		14471.	IN.A.			
	size of riser/down-comer	N.A.	N.A.	N.A.			
	Number of hydrants per floor Hose Box	N.A.	N.A.	N.A.			
		N.A.	N.A.				
2	Yard Hydrants.						
	Total number of hydrants	N.A.	N.A.	N.A.			
	Hose Box	N.A.	N.A.				
3	Pumping Arrangements.						
	➢ Ground Level	N.A.	N.A.	I NI A			
	Discharge of main Pump	N.A.	N.A.	N.A.			
	Head of Main Pump	N.A.	N.A.	N.A.			
	Number of main pumps	N.A.		N.A.			
	Jockey pump out put	N.A.	N.A.	N.A.			
	Jockey pump head	N.A.	N.A.	N.A.			
	Standby pump out put	N.A.	N.A.	N.A.			
	Standby pump Head	N.A.	N.A.	N.A.			
	Auto Starting /Manual stopping	N.A.	N.A.	N.A.			
Personal Contraction of the Pe	Pump House Access	N.A.	N.A.	N.A.			
	> Terrace Level	01no.	N.A.	N.A.			
	Discharge of pump	450LPM	01no.	MR.			
	> Head of the Pump	40m	450LPM	MR			
	Power supply	N.A.	40m	MR			
	Auto Starting of pump	13.77.	N.A.	N.A.			

h

Bishop Boys Diocesan School, 6-B, Rajpur Road, Delhi-54.

14	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	N.A.	N.A.	N.A.	
	Draw-off connection Fire service inlet Access to tank Overhead Tank capacity	N.A.	N.A.	N.A.	
		N.A.	N.A.	N.A.	
		N.A.	N.A.	N.A.	
		10000 liters	10000 liters	.MR	
15	Exit Signage.	Required	Provided	MR.	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N.A.	N.A.	N.A.	
	Pressurization of Lift lobby Communication in lift car Firemen's grounding switch Lift Signage	N.A.	N.A.	N.A.	
		N.A.	N.A.	N.A.	
		N.A.	N.A.	N.A.	
		N.A.	N.A.	N.A.	
17	Standby power supply	N.A.	N.A.	N.A.	
18	Refuge Area.				
	Total area	N.A.	N.A.	N.A.	
	Location	N.A.	N.A.	N.A.	
19	Fire Control Room				
	Detector system panel	N.A.	N.A.	N.A.	
	Flow switch panel	N.A.	N.A.	N.A.	
	PA system panel Batter backup Building Floor Plans	N.A.	N.A.	N.A.	
		N.A.	N.A.	N.A.	
		N.A.	N.A.	N.A.	
20	Special Fire Protection systems for protection of special Risks, if any:	N.A.	N.A.	N.A.	

The fire protection systems provided in the building were test checked and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the NOC issued vide letter No.F.6/DFS/MS/2011/555 dated29.03.2011 rehewal under rule 35 of the Delhi Fire Service Rule 2010 is recommended.

Signature of the Inspecting Officer

Name

Vedpal

Designation

ADO

D.O.(Central)

28/11/14