GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID:cfohq.dlfire@nic.in

No F 6/DFS/MS/GH/2014/MD2/595

Dated 0 9/05/14

FIRE SAFETY CERTIFICATE

Certified that the **Banana Leaf Restaurant at N-12**, **Connaught Place**, **New Delhi** running at ground floor and Building is comprised of ground floor + 2 upper floors was granted NOC by this department vide letter No. F6/MS/DFS/EH/2010/2814 dated 28-09-2010. The premises was re-inspected by the officers concerned of this department on 28-04-2014 in the presence of Mr. Navin Kumar (Manager) and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class Group D Assembly Building** with effect from -5-2-1-2014 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G. C. Misra) Chief Fire Officer Delhi fire Service Ph – 011-23414333

Copy to:-

1. Banana Leaf Restaurant at N-12, Connaught Place, New Delhi.

2. Medical officer of Health, Health Department, Palika Kendra, New Delhi – 110001 No.D-200/ MOH/CSI (Lic)SI-1 dated 02/04/2014.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

-N/h-

INSPECTION REPORT

1. Name & address of the building : Banana Leaf Restaurant at N-12 Connaught Place, New Delhi.

2. Type of Occupancy : Assembly Building (Restaurant) Ground floor

3. Type of Case : Renewal

4. Details of previous NOC : F6/MS/DFS/EH/2010/2814 dated 28/09/2010

5. Fire Safety directives Letter No. : NA

6 Date of inspection : 28/04/2014

7 Name of the Inspecting Officer : Sh. Gurmukh Singh (DO/CD) & Sh. M. K. Sharma (ADO/CC)

8 Name and designation of Officer

from the building side : Mr. Navin Kumar (Manager)

9. Year of Construction : old Heritage Bldg.

10. Applicant's letter No. : No. D 200/ MOH/CSI/ (Lic)/SI-I dated 02/04/2014

No Minimum standards on fire prevention	Requirements	Provided at site	Remarks MR/NMR
and fire safety U/R 33			
. Access of building		12 Mtr.	MR
Road width	9 Mtr.	NA	NA
Gate width	NA		NA
Width of internal road	NA	NA	
The state of the s	Number, width, Type & Arrangements of exits		
a. Number of staircases		1 2 2 2 1 1 A D	MR
	v 125	me 120 Mold	NA
Basements	NA	NA	. INA
b.Width of staircases		274	NA
• Upper floors	NA	NA	NA
Basements	NA	NA	TVIX
c. Protection of exits			NTA.
	NA	NA	NA
• Fire check door	NA	NA	NA
Pressurization			

h man

			0.1	MD
	d. No of continuous staircase to terrace	01	01	MR
	e. Width Of Corridor	NA	NA	NA
	f. Door Size	1.70 Mtr.	1.70 Mtr.	MR
	Compartmentation			,
	Fire check door	NA	NA	NA
	 Sealing of electrical shafts 	NA	NA	NA
	 Fire Rating of shaft door 	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
	Smoke managements System			
an.	Basements	NA	NA	NA
	Upper floors (Ground floor)	12 ACPH	NATURAL	MR
5	Fire Extinguishers			
	Total numbers	4 Nos.	6 Nos.	MR
	• Types	ABC, CO ₂ , Wco ₂	ABC, CO ₂ , Wco ₂	MR
	IS marking	Required	Provided	MR
6	First – Aid Hose Reels			
	Total numbers on each floor	01	01	MR
	 Length of hose reel hose 	30 Mtr.	30 Mtr.	MR
	Nozzle diameter	05 MM	05 MM	MR
7	Automatic fire detection and alarming system			
	Type of detectors	NA	NA	NA
	 Location of Main Panel 	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System	NA	NA	NA
10	Automatic Sprinkler		2	
10	Basements	NA	NA	NA
	Upper Floor	Required	Provided	MR
	Sprinkler above false ceiling	NA	NA	NA
	Sprinklet acciditation			





行的本列

-H/6-

	Internal Hydrants			274
	Size of riser/down- comer	NA	NA	NA
	 Number of hydrants per floor 	NA	NA	NA
	Hose Box	NA	NA	NA
12	Yard Hydrants			
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
3	Pumping Arrangements			
	o Ground Level			
	Discharge of main pump	NA	NA	NA
	Head of main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	Jockey pump out put	NA	NA	NA
	Jockey pump head	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	Standby Pump Head	NA	NA	NA
	auto Staring/Manual stopping	NA	NA	NA
	Pump House Access	NA	NA	NA
	o Terrace level			,
	Discharge of pump	450 LPM	450 LPM	MR
	Head of the pump	30 Mtr.	30 Mtr.	MR
	Power supply	Required	Provided	MR
	Auto starting of pump	Required	Provided	MR
	*			VI
14	Captive water Storage for fire fighting NA		NA	NA
	Under ground tank capacity	NA	NA	NA
	Draw of connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	 Access to tank 	Required	Provided	MR
	Overhead Tank capacity	2500 Ltr.	2500 Ltr.	MR
15	Exit Signage	Required	Provided	MR
16	Provision of Lifts	NA	NA	NA

h

Men

H17-

Bahana Leaf Restaurant at N-12 CP MD

	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of lift lobby	NA	NA	NA	
	Communication in lift Car	NA	NA	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	Lift Signage	NA	NA	NA	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area				
	Total area	NA	NA	NA	
	Location	NA	NA	NA	
19	Fire control room	V			
	Detector system panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Batter backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20	Special Fire Protection Systems for	Required	ABC, Co ₂	MR	
	Protection of special Risks, if any;		5		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the NOC issued vide letter no. F6/MS/DFS/EH/2010/2814 dated 28/09/2010, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended please.

Name :- Sh. Gurmukh Singh

Designation :-DO(CD)

Name:- Sh. M. K. Sharma Designation :- A. D.O. (CC)