GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

Fax:- 011-23412593

E-mail ID:cfohq.dlfire@nic.in

No F 6/DFS/MS/GH/2014/H02/594

Dated 0 8/05/14

FIRE SAFETY CERTIFICATE

Certified that the Sarvana Bhawan Restaurant at 46, Janpath, Connaught Place, New Delhi running at ground floor plus Mezzanine floor and Building is comprised of ground floor + 2 upper floors was granted NOC by this department vide letter No. F6/DFS/MS/2011/EH/727 dated 21-04-2011. The premises was re-inspected by the officers concerned of this department on 28-04-2014 in the presence of Mr. Sami Singh (Manager) and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class Group D Assembly Building with effect from -2/-2014 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. G. C. Misra) Chief Fire Officer Delhi fire Service Ph – 011-23414333

Copy to:-

- 1. Sarvana Bhawan Restaurant at 46, Janpath, Connaught Place, New Delhi.
- 2. Medical officer of Health, Health Department, Palika Kendra, New Delhi 110001 No. MOH/195/D/CMO (Lic.)SI-V dated 27/03/2014.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time. The owner / occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	TATOPEOT	TON DEDODT		
	-	ION REPORT		lu Dlaga
& address of the building	& address of the building : Sarvana Bhawan Restaurant at 46, Janpath, Connaught Place,			
	New Delh	i.		
of Occupancy	: Assembly	Building Gr.+2floor	(Restaurant)Gr. + Me	ezzanine floo
	: Renewal			
	: F6/DFS/MS/2011/EH/727 dated 21/04/2011			
	: NA			
	: 28/04/201	4		
_			& Sh. M. K. Sharma	(ADO/CC)
		Turin Singing		
from the building side	: Mr. Sam	Singh (Manager)		
or of Construction				
plicant's letter No.	: No. MOI	H/195/D/CMO (Lic.)/	SI-Vdated 27/03/2014	4
Minimum standards on fire	prevention	Requirements	Provided at site	Remarks
and fire safety U/R 33			*	MR/NMR
Access of building				, AD
Road width		9 Mtr.		MR
Gate width		NA	1	NA
Width of internal r	oad	NA	NA	NA
Number, width, Type & Arrangements of exits				
a. Number of staircases			2 Nos	MR
• Upper floors				NA
• Basements		NA	INA	1112
b. Width of staircases			10 & 107 Mtr	MR
• Upper floors	M	1	NA	NA
Basements		NA	IVA	1,22
c. Protection of exits				
	of Occupancy of Case ils of previous NOC Safety directives Letter No. of inspection e of the Inspecting Officer e and designation of Officer from the building side of Construction uplicant's letter No. Minimum standards on fire and fire safety U/R 33 Access of building Road width Gate width Width of internal r Number, width, Type & A a. Number of staircases Upper floors Basements b. Width of staircases	New Delhor of Occupancy : Assembly of Case : Renewal : Renewal : F6/DFS/M : F6/DFS/M : NA of previous NOC : F6/DFS/M : NA of inspection : 28/04/2010 : Sh. Gurn e and designation of Officer from the building side : Mr. Saminar of Construction : old Heritary of Construction : No. MOF Minimum standards on fire prevention and fire safety U/R 33 Access of building • Road width • Gate width • Width of internal road Number, width, Type & Arrangements of a. Number of staircases • Upper floors • Basements b. Width of staircases	& address of the building : Sarvana Bhawan Restaurant at 4 New Delhi. of Occupancy : Assembly Building Gr.+2floor of Case : Renewal ils of previous NOC : F6/DFS/MS/2011/EH/727 date Safety directives Letter No. : NA of inspection : 28/04/2014 e of the Inspecting Officer : Sh. Gurmukh Singh (DO/CD) e and designation of Officer from the building side : Mr. Sami Singh (Manager) ar of Construction : old Heritage Bldg. ir of Construction : No. MOH/195/D/CMO (Lic.)// Minimum standards on fire prevention and fire safety U/R 33 Access of building • Road width • Gate width • Width of internal road Number, width, Type & Arrangements of exits a. Number of staircases • Upper floors • Basements b. Width of staircases	& address of the building : Sarvana Bhawan Restaurant at 46, Janpath, Connaug New Delhi. of Occupancy : Assembly Building Gr.+2floor (Restaurant)Gr. + Medical Section of Case : Renewal : F6/DFS/MS/2011/EH/727 dated 21/04/2011 Safety directives Letter No. : NA : N

h most

-N-0

	• Fire check door	NA	NA	NIA	
	 Pressurization 	NA	NA	NA	
	d. No of continuous staircase to terrace	01	01	NA	
	e. Width Of Corridor	NA	NA	MR	
	f. Door Size	2 Mtr.	INA	NA	
3.	Compartmentation	2 IVIU.	2 Mtr.	MR	
	Fire check door	NA	271		
	 Sealing of electrical shafts 	100 100 100	NA	NA	
		NA	NA	NA	
	The Rating of shall door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	Fire Dampers	NA	NA	NA	
1	Smoke managements System				
	• Basements	NA	NA	NA	
	• Upper floors	12 ACPH	NATURAL	MR	
	Fire Extinguishers				
2	Total numbers	14 Nos.	4 Nos.	MR	
	• Types	ABC, CO ₂ , Wco ₂	ABC, CO ₂ , Wco ₂	MR	
	IS marking	Required	Provided	MR	
)	First – Aid Hose Reels				
	Total numbers on each floor	02	02	MR	
	 Length of hose reel hose 	30 Mtr.	30 Mtr.	MR	
	Nozzle diameter	05 MM	05 MM	MR	
	Automatic fire detection and alarming system				
	Type of detectors	NA	NA	NA	
	 Location of Main Panel 	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA NA	
	Alternate source of power	NA	NA NA		
	Hooters' Location	NA		NA	
	MOEFA		NA	NA	
		Required	Provided	MR	
	Public Address System	NA	NA	NA	
	Automatic Sprinkler		0 =		
	Basements	NA	NA	NA	

In mon

- N-9

	Upper Floor	D	anestick and	
	Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants	B NA	NA	NA
	Size of riser/down- comer			
	Number of hydrants per floor	100 MM	100 MM	MR
	Hose Box		02	MR
12	Yard Hydrants	02	02	MR
	Total number of hydrants			
	Hose Box	NA	NA	NA
3 P	umping Arrangements	NA	NA	NA NA
	Ground Level			IVA
	Discharge of main pump	NA	NA	27.
	ricad of main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	 Jockey pump out put 	NA	NA	NA
	 Jockey pump head 	NA	NA	NA
	 Standby Pump out put 	NA	NA NA	NA
	 Standby Pump Head 	NA	NA NA	NA
	 auto Staring/Manual stopping 	NA		NA
	 Pump House Access 	NA	NA NA	NA
	Terrace level		NA	NA
•	Discharge of pump	180 & 450 LPM	190 0 450	
•	Head of the pump	30 Mtr.	180 & 450 LPM	MR
	Power supply	Required	30 Mtr.	MR
•	Auto starting of pump	Required	Provided	MR
	Illura Colonia	1	Provided	MR
Capti	ve water Storage for fire fighting	NA		
•	Under ground tank capacity	NA	NA	NA
•	Draw of connection	NA	NA	NA
•	Fire service inlet	NA	NA	NA
•	Access to tank		NA	NA
•	Overhead Tank capacity	Required	Provided	MR
	pucity	5000 Ltr.	5000 Ltr.	MR

men

Sarvana Bhawan Restaurant at 46, Janpath CPND

15	Exit Signage	Required	Provided	MR	
16	Provision of Lifts	NA	NA	NA	
	 Pressurization of Lift Shaft Pressurization of lift Johny 	NA	NA	NA	
	Pressurization of lift lobbyCommunication in lift Car	NA	NA	NA	
		NA	NA	NA	
	Fireman's Grounding SwitchLift Signage	NA	NA	NA	
1.7		NA	NA	NA	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area				
	Total area	NA	NA	NA	
	• Location	NA	NA	NA	
19	Fire control room				
	Detector system panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Batter backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20	Special Fire Protection Systems for Protection of special Risks, if any;	Required	ABC, Co ₂	MR	

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/2011/EH/727 dated 21/04/2011 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Name :- Sh. Gurmukh Singh

Designation:-DO(CD)

Name:- Sh. M. K. Sharma Designation :- A. D.O. (CC)