

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.**

E-mail:- cfohq.dlfire@nic.in
No. F.6/DFS/MS/EH/2014/ 52/1196


Fax:- 011-23412593

Dated: 15/09/14

FIRE SAFETY CERTIFICATE

Certified that the **Maya Tandoori Restaurant**, J-2/3, B.K. Dutt Market, Rajouri Garden, New Delhi-110027 comprised of ground floor plus two upper floors & basement, but restaurant running at ground floor plus two upper floors only. The restaurant building was issued NOC by this department vide letter No. F6/DFS/MS/EH/2011/1109 dated 06.06.2011 owned/occupied by M/s Maya Tandoori Restaurant. The Restaurant building was re-inspected by the officers concerned of this department on 21.08.2014 in the presence of Sh. Satish Kumar (Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building (**at ground floor plus two upper floors only**) is fit for occupancy class Group D assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....15/09/14.....at New Delhi.



(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
Ph:- 011-23414333

OK 500
15/9/14

Copy to:-

1. The Manager,
Maya Tandoori Restaurant
J-2/3, B.K. Dutt Market,
Rajouri Garden, New Delhi-110027.
2. Dy. Health Officer,
South Zone Municipal Corporation,
Public Health Department, West Zone,
Vishal Enclave, New Delhi.
(D-1353/DHO/WZ/2014 dt. 16.06.14)

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. Basement shall be used as per the building bye laws.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

116

Ground plus two upper floors & basement but restaurant is running at ground and two upper floors
(Tandoori Restaurant, J-2/3, B.K. Dutt Market, Rajouri Garden, ND-110027)

INSPECTION REPORT

1. Name & address of the building : Maya Tandoori Restaurant, J-2/3, B.K. Dutt Market, Rajouri Garden, ND-27
2. Type of Occupancy : Group D (Assembly)
3. Type of Case : Renewal
4. Details of Previous NOC : F6/DFS/MS/EH/2011/1109 dated 06.06.2011
5. Fire Safety directives letter No : Nil.
6. Date of inspection : 21.08.2014
7. Name of Inspecting Officer : D.O. S.K. Tomar and A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Sh. Satish Kumar (Manager)
9. Year of Construction : Before 2009.
10. Applicant's letter No. : Form-J dated 17.06.2014 and D-1353/DHO/WZ/2014 dt. 16.06.14

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	<p>Accessible</p> <p style="text-align: center;">—</p> <p style="text-align: center;">—</p>	<p>12 mtrs</p> <p>130 & 125 cms</p> <p style="text-align: center;">—</p>	<p>M/R</p> <p>M/R, Old case</p> <p style="text-align: center;">—</p>
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	<p>02 No's.</p> <p>02 No's.</p>	<p>02 No's</p> <p>02 No's</p>	<p>M/R</p> <p>M/R</p>
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	<p style="text-align: center;">—</p> <p style="text-align: center;">—</p>	<p>102 & 125 cms</p> <p>102 & 125 cms</p>	<p>M/R, Old case</p> <p>M/R, Old case</p>
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	<p>Required</p> <p style="text-align: center;">—</p>	<p>Provided</p> <p style="text-align: center;">—</p>	<p>M/R</p> <p style="text-align: center;">—</p>
	d. No. of continuous staircases to terrace		<p>one</p>	<p style="text-align: center;">—</p>
	e. Width of Corridor		<p>Opening in hall</p>	<p style="text-align: center;">—</p>
	f. Door Size		<p>01 mtr</p>	<p>M/R, Old case</p>
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door 	<p>Required</p>	<p>Provided</p>	<p>M/R</p>
	<ul style="list-style-type: none"> • Sealing of electrical shafts 	<p>Required</p>	<p>Provided</p>	<p>M/R</p>
	<ul style="list-style-type: none"> • Fire Rating of shaft door 	<p>N/A</p>	<p>N/A</p>	<p>N/A</p>
	<ul style="list-style-type: none"> • Water Curtain 	<p>N/A</p>	<p>N/A</p>	<p>N/A</p>
	<ul style="list-style-type: none"> • Fire Dampers 	<p>N/A</p>	<p>N/A</p>	<p>N/A</p>
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements 	<p>30 a/c per hour</p>	<p>Exhaust Fans</p>	<p>M/R</p>

N/A

Ground plus two upper floors & basement but restaurant is running at ground and two upper floors
(Tandoori Restaurant, J-2/3, B.K. Dutt Market, Rajouri Garden, ND-110027)

	<ul style="list-style-type: none"> Upper floors 	12t a/c per hour	Exhaust Fans	M/R
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers Types IS marking 	Two no's / floor ABC/CO2/WCO2	Provided	M/R
			Provided	M/R
		ISI marked	ISI marked	M/R
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	one 30 mtrs 5 mm	Provided	M/R
			Provided	M/R
			Provided	M/R
7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Smoke & Heat	Provided	M/R
		—	Ground Floor	M/R
		—	—	—
		Required	Provided	M/R
			Near exits	M/R
8.	MOEFA	Required	Provided	M/R
9.	Public Address System	Required	Provided	M/R
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basement Ground & Upper Floors Sprinkler above false ceiling 	Required	Provided	M/R
		Required	Provided	M/R
		—	—	—
11.	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	100mm	Provided	M/R
		One	Provided	M/R
		One	Provided	M/R
12.	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	—	—	—
		—	—	—
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/Manual Stopping 			
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A

S

N/8

Ground plus two upper floors & basement but restaurant is running at ground and two upper floors
(Tandoori Restaurant, J-2/3, B.K. Dutt Market, Rajouri Garden, ND-110027)

	<ul style="list-style-type: none"> ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	N/A	N/A	N/A
		450 LPM & 180LPM	Provided	M/R
		40 mtrs each	Provided	M/R
		Required	Provided	M/R
		Required	Provided	M/R
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	N/A	N/A	N/A
		N/A	N/A	N/A
		Required	Provided	M/R
		N/A	N/A	N/A
		5000 ltrs	Provided	M/R
		Required	Provided	M/R
15.	Exit Signage.			
16.	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		Required	Provided	M/R
		Required	Provided	M/R
		Required	Provided	M/R
		Required	Provided	M/R
17.	Standby power supply	Required	Provided 180 KVA	M/R
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Battery backup • Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

N/9

Ground plus two upper floors & basement but restaurant is running at ground and two upper floors
(Tandoori Restaurant, J-2/3, B.K. Dutt Market, Rajouri Garden, ND-110027)

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number F6/DFS/MS/EH/2011/1109 dated 06.06.2011 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note: - The undertaking letter is placed on C-39 given by the Manager, regarding use of lifts from Ground floor to upper floors and not in basements.


S.K. Tomar
07/07/14

Signature of Inspecting Officer

Name:- S.K. Tomar

Designation:- Divisional Officer


Sandeep
07/07/14

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Dy.C.F.O. (South Zone)

