## FORM 'H'

## FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub – rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI** 

No. FEIDFJ/ms/2014/62/1197

Dated: 12 19/14

## FIRE SAFETY CERTIFICATE

Certified that the Toast Restaurant located at SF - 42, 43, 44, West Gate Mall, Shivaji Place, Rahouri Garden, New Delhi - 110027 was issued FSC vide Letter No. F6/DFS/MS/EH/2011/1137 dated 09-06-2011. The West Gate Mall has already issued FSC vide letter no. F6/DFS/MS/2014/WZ/1011 dated 11-08-2014. The premises was re inspected by the officers concerned of this department on 05-09-2014 in the presence of Mr. Mukul (Restaurant Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from 12 1 4 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12/9/14 at New Delhi by.

(Dr. G. C. Misra) Chief Fire Officer. Ph - 011-23414333.

Copy to:-

1. Sh. Tarun Rai Arora (Proprietor) The Toast Restaurant, SF - 42, 43, 44, West Gate Mall, Shivaji Place, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner / occupier shall submit a declaration every year in the Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

## **INSPECTION REPORT**

 Name & address of the building: Toast Restaurant, SF – 42, 43, 44, West Gate Mall, Shivaji Place, New Delhi – 110027.

2. Type of Occupancy

3. Type of Case : Renewal (Situated in Mall already issued NOC

: Assembly

vide letter no. F6/DFS/MS/2014/WZ/1011 dated 11-08-2014)

4. Details of previous NOC : Letter No. F6/DFS/MS/EH/2011/1137 dated

09-06-2011

5. Fire Safety directives Letter No.: FSC Issued to the mall vide letter no. F6/DFS/MS/2014/WZ/1011 dated 11-08-2014

6. Date of inspection : 05-09-2014

7. Name of the Inspecting Officer: Sunil Chawdhary DO (W) & Mukesh Verma, ADO (MN)

8. Name and designation of Officer

from the building side : Sh. Mukul (Restaurant Manager)

9. Year of Construction : 2011

10. Applicant's letter No. : Nil Dated 26-08-2014

	T.F.			
S	Minimum standards on fire	BBL	Provided at	Remarks
No	prevention and fire safety U/R	Requirements	site	MR/NMR
	33			
1.	Access of building			3 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	<ul> <li>Road width</li> </ul>	6 m	Provided	MR
	Gate width	NA	NA	NA
	<ul> <li>Width of internal road</li> </ul>	NA	NA	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	<ul> <li>Upper floors</li> </ul>	2	Provided	MR
	<ul> <li>Basements</li> </ul>	NA	NA	NA
	b. Width of staircases			1
	<ul> <li>Upper floors</li> </ul>	Old Case	Old Case	MR
	<ul> <li>Basements</li> </ul>	NA	NA	NA
	c. Protection of exits			
	Fire check door	NA	NA	NA
9	<ul> <li>Pressurization</li> </ul>	NA	NA	NA
	d. No of continuous	NA	NA	NA
	staircase to terrace			
	e. Width Of Corridor	NA	NA	NA
	f. Door Size	Old Case	Old Case	MR

3.	Compartmentation	And the second s			
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	<ul> <li>Fire Rating of shaft door</li> </ul>	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	E - SOURCE SEE ALT DELL'S	NA	NA	NA	
4.	• Fire Dampers Smoke managements System				
4.	Basements	30 a/c per hour	NA	NA	
	<ul><li> Upper floors</li></ul>	12 a/c per hour	Provided	MR	
5.	Fire Extinguishers				
	Total numbers	02 nos. each	Provided	MR	
	<ul> <li>Types</li> </ul>	type	Provided	MR	
	IS marking	ABC & CO <sub>2</sub> ISI marked	Provided	MR	
6.	First – Aid Hose Reels				
	Total numbers on each	Required	Provided	MR	
	floor	30 m	Provided	MR	
	<ul><li>Length of hose reel hose</li><li>Nozzle diameter</li></ul>	5 mm	Provided	MR	
7.	Automatic fire detection and alarming system				
	Type of detectors	Smoke	Provided	MR	
	<ul> <li>Location of Main Panel</li> </ul>	Required	Provided	MR	
	Location of Repeater     Panel	NA	NA	NA	
	Alternate source of power	Required	Provided	MR	
	Hooters' Location	Required	Provided	MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	NA	Provided	NA	
10.	Automatic Sprinkler System				
	<ul><li>Basements</li><li>Upper Floor</li></ul>	Not Applicable	Not Applicable	Not Applicable	
	• Sprinkler above false	Required	Provided	MR	
	ceiling	Required	Provided	MR	
11.	Internal Hydrants: Common with the mall				
	Size of riser/down-	150 mm	Provided	MR	
	comer  Number of hydrants per	Required	Provided	MR	
	floor  Hose Box	Required	Provided	MR	
12.	Yard Hydrants				
14.	Total number of	NA	NA	NA	
	hydrants  Hose Box	NA	NA	NA	

- 8

1/12

			<del></del>	
	<ul><li> Ground Level</li><li> Discharge of main</li></ul>	NA	Common	NA
	-		with the mall	
	pump	NA	Common	NA
	> Head of main pump		with the mall	
	7 Head of main pains	NA	Common	NA
	Number of main pumps		with the mall	
	7 Tumber of man pump	NA	Common	NA
	Jockey pump out put		with the mall	,
		NA	Common	NA
	Jockey pump head	*	with the mall	
		NA	Common	NA
	Standby Pump out put	107	with the mall	
		NA	Common	NA
	Standby Pump Head		with the mall	
		NA	Common	NA
	Auto Staring/Manual		with the mall	
	stopping	NA	Common	NA
	Pump House Access		with the mall	
	<ul> <li>Terrace level</li> </ul>			
		900 lpm	Common	MR
	Discharge of pump		with the mall	
		40 m	Common	MR
	Head of the pump		with the mall	
		Required	Common	MR
	Power supply		with the mall	
	6	Required	Common	MR
	> Auto starting of pump		with the mall	
14.	Captive water Storage for fire fig	ghting: Common	with the mall	TNIA
	<ul> <li>Under ground tank</li> </ul>	NA	2,50,000	NA
	capacity		litres	NIA
	Draw off connection	NA	Provided	NA
	> Fire service inlet	Required	Provided	MR
	> Access to tank	NA	Provided	NA
	<ul> <li>Overhead Tank capacity</li> </ul>	10, 000 litres	30,000	MR
			Litres	
		D '-1	Provided	MR
15	Exit Signage	Required	Provided	IVIIX
16.	Provision of Lifts	NTA.	NIA	NA
	> Pressurization of Lift	NA	NA	INA
	Shaft	NIA	NA	NA
	> Pressurization of lift	NA	INA	INC
	lobby	NIA	NA	NA
	Communication in lift	NA	INA	INCI
Connect Control	Car	NIA	NA	NA
Coleman State of Stat	Fireman's Grounding	NA	INA	INT
	Switch  Lift Signage	NA	NA	NA
	> Lift Signage	INA	A	
17.	Standby power supply	Required	Provided	MR

18.	Refuge Area		NIA	NA
	> Total area	NA	NA	
	Location	NA	NA	NA
19.	Fire control room			NIA
	Detector system panel	NA	NA	NA
	> Flow Switch Panel	NA	NA	NA
	> PA System Panel	NA	NA	NA
	> Battery backup	NA	NA	NA
	> Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems	NA	NA	NA
	for Protection of special Risks, if any;			were test checked and

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/EH/2011/1137 dated 09-06-2011 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name MUKRSH VERMA

Name

Designation ADD (MN)

Designation