GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

E-mail:- cfohq.dlfire@nic.in No.F.6/DFS/MS/School/2015/52/190

Fax:- 011-23412593

Dated: 10/02/15

FIRE SAFETY CERTIFICATE

Certified that the building of Govt. Co-ed Secondary school, Bindapur, Pocket IV, New Delhi 110059, is comprised of ground plus one upper floor, was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2011/3568 dated 16.12.2011. The School building was re- inspected by the officer concerned of this department on 24.01.2014 in the presence of Sh. Kailash Chand Meena (Vice Principal) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(DR. G.C. MISRA) CHIEF FIRE OFFICER **DELHI FIRE SERVICE**

Ph:- 011-23414333

Copy to:-

1. The Principal,

Govt. Co-ed Secondary school, Bindapur, Pocket IV, New Delhi 110059.

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

3. Executive Engineer, CBMC M-122(D.C.), ITI campus, Pusa, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available www.dfs.delhigovt.nic.in.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

214

Ground plus one upper floor (Govt. Co-ed Secondary school, Bindapur, Pocket IV, New Delhi 110059

		INSPECTIO	N REPORT	N	6.
1. 2.	Name & address of the building: Type of Occupancy:	<u>INSPECTION REPORT</u> Govt. Co-ed Secondary school, Bindapur, Pocket IV, New Delhi 110059. Educational			
3.	,	Renewal			
4.	Details of Previous NOC :	F.6/DFS/MS/So	chool/2011/3568 d	ated 16.12.2011.	
5.	Fire Safety directives letter No : N/A				
6. 7.	. 24.01.2015				
8.	Name of Inspecting Officer : Name and designation of officers	Duggal			
0.	From the building side :	Cl. 17.11 1 C	11 136 67		
9.	Year of Construction	Sn. Kailash C	Chand Meena (Vic	ce Principal)	
	Applicant's letter No.		10/10/100/100	A 10 10 10 10 10 10 10 10 10 10 10 10 10	
No.	Minimum Standards on fire pre	ZU(FF)/DB/ CB	MC/M-122(N)/?WI	D/2014-15/20 date	
	fire safety U/R 33	vention and	Dir. Of Edu. Circular dt.	Provided at	Remarks
2			01.03.2011	site	MR/NMR
	Access to building	a * ,	01.05.2011		
	 Road width 		Accessible	6.0 mtrs	M/R
	 Gate width 		,	5.5 mtrs.	IVI/ K
	 Width of internal road 			2	
	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases				
	 Upper Floors 		02 No's	02 No's	M/R
	 Basements 		N/A	N/A	
	b. Width of staircases		17/21	IN/A	No basemen
	Upper Floor			1 40 % 1 47	
	Basements		21/4	1.48 & 1.47 mtrs.	M/R, old cas
	c. Protection of exits		N/A	N/A	No basement
	Fire check door			Mariana W	
14	 Pressurization 		N/A	N/A	N/A
8		-	N/A	N/A	N/A
.0	d No of continue				
4	d. No. of continuous staircases to terrace		N/A	N/A	N/A
	e. Width of Corridor			1.73 mtrs	M/R
	S. D. S.		N/A	97 cms	M/R
9.	f. Door Size Compartmentation	· · · · · · · · · · · · · · · · · · ·		(Double Door)	
	Fire check door				1
	 Sealing of electrical shafts 		N/A	N/A	N/A
		st. in	N/A	N/A	N/A
, -	Fire Rating of shaft doorWater Curtain	n n	N/A	N/A	N/A
	Fire Dampers.		N/A	N/A	N/A
	The bumpers.		N/A	N/A	
	moke Management System		INIA	IN/A	N/A

2/6

Ground plus one upper floor (Govt. Co-ed Secondary school, Bindapur, Pocket IV, New Delhi 110059)

	Upper floors	N/A	Natural Ventilation	M/R
5.	Fire Extinguishers			
	Total numbers	08 no's	Provided	M/R
	• Types	ABC/CO2 type	Provided	M/R
	IS marking	ISI marked	ISI marked	M/R
6.	First-Aid Hose Reels			
	 Total numbers on each floor 	N/A	N/A	N/A
	 Length of hose reel hose 	N/A	N/A	N/A
	Nozzle diameter	N/A	N/A	N/A
7.	Automatic fire detection and alarming system			
*	Type of detectors	N/A	N/A	N/A
*	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
		N/A	N/A	N/A
0	Hooters' Location			
8. 9.	MOEFA Dublic Address Section	N/A	N/A	N/A
9. 10.	Public Address System Automatic Sprinkler System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
		N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
4 4 1	Sprinkler above false ceiling			
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			5
	Total number of hydrants	N/A	N/A	N/A
[S	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	×		
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A N/A	N/A
	Standby Pump out putStandby Pump Head	N/A N/A		
, A	Standby Fullip nead		N/A	N/A
	> Standby Lump Head	N/A	N/A N/A	jy/.

N/6

Ground plus one upper floor (Govt. Co-ed Secondary school, Bindapur, Pocket IV, New Delhi 110059)

	Auto Starting/Manual Stopping	N/A	N/A	NT/A
			11/74	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump Head of the pump	N/A	N/A	N/A
	read of the pullp	N/A	N/A	N/A
	Tower Supply	N/A	N/A	N/A
-	Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			8
	Underground tank capacity	N/A		
	> Draw-off connection		N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.			
	 Pressurization of Lift Shaft 	NI/A	No L	ift
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
,	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	Total AreaLocation	N/A	N/A	N/A
	25041011	N/A	N/A	N/A
9.	Fire Control Room			- 1/4.4
	Detector System Panel	NI/A		2 do
	Flow Switch Panel	N/A	N/A	N/A
1 1	PA System Panel	N/A	N/A	N/A
	· copy of the second	27/4	27/	
		N/A	N/A	N/A
	Battery backup	N/A N/A	N/A N/A	N/A N/A

Ground plus one upper floor (Govt. Co-ed Secondary school, Bindapur, Pocket IV, New Delhi 110059)

Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number <u>F.6/DFS/MS/School/2011/3568</u> dated <u>16.12.2011</u> renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Sandel

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Signature of Inspecting Officer

Name

Designation

