GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in No. F.6/DFS/MS/GH/2015/ \$2 /(2/6 Fax: - 011-23412593 Dated: 10/07/

FIRE SAFETY CERTIFICATE

Certified that the **Janak Guest House**, C-2/6, Janakpuri, New Delhi – 110058 comprised of Basement, Stilt, Upper ground floor, First floor & Second floor, using basement as hall/storage, ground floor as Parking, upper ground floor as Hall, first floor having Eight guest rooms, second floor having seven guest rooms & Kitchen (Total Fourteen guest rooms). Above guest house are owned/occupied by Sh. M.R Motsara. The guest house building was inspected by the officers concerned of this department on 18.06.2015 in the presence of Sh. M.R Motsara and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (**Fourteen Guest Rooms only**) is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- The Joint commissioner of Police, Licensing Unit, First Floor, P.S. Defence Colony, New Delhi. (1015-19/JointC.P./Lic.(H) dated 12.01.2015)
- 2. Sh. M.R Motsara
 Janak Guest House, C-2/6, Janakpuri,
 New Delhi 110058.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per the building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of Basement, Stilt, Upper ground, First floor & Second Floor. (Janak Guest House, C-2/6, Janakpuri, New Delhi – 110058)

INSPECTION REPORT

1. Name & address of the building: Janak Guest House, C-2/6, Janakpuri, New Delhi – 110058.

. Type of Occupancy : Residential (Guest House)

Type of Case : New
 Details of Previous NOC : N/A
 Fire Safety directives letter No : N/A

6. Date of inspection : 18.06.2015

7. Name of Inspecting Officer : D.O. S.K. Tomar and A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Sh. M.R. Motsara 9. Year of Construction : Before 2005

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building						
	Road width	Accessible	12.0 mtrs	M/R			
	Gate width		04 mtrs(02 No.'s)	M/R			
	 Width of internal road 						
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	 Upper Floors 		One	M/R (Old Bldg.)			
	 Basements 		Two	M/R			
	b. Width of staircases						
	Upper FloorBasements		125 cms	M/R			
			125 & 125 cms	M/R			
	c. Protection of exits						
	Fire check door	Required	Provided	M/R			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of continuous staircases to	N/A	One	N/A			
	e. Width of Corridor f. Door Size	14/71	165 cms.	M/R			
		_	90 cms.	M/R (Old Bldg.)			
3.	Compartmentation						
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
1.	Smoke Management System						
	Basements	Required	Exhaust fans are provided	M/R			

Building is comprised of Basement, Stilt, Upper ground, First floor & Second Floor. (Janak Guest House, C-2/6, Janakpuri, New Delhi – 110058)


	Upper floors	N/A	Natural Ventilation	M/R	
		1			
•	Fire Extinguishers	Two at each Floor	08 No's	M/R	
	Total numbers	WIGO / CO tune	Provided) (/D	
	 Types 	W/CO ₂ / CO ₂ type	Provided	M/R	
	IS marking	ISI marked	ISI marked	M/R	
	First-Aid Hose Reels	27/4	N/A	N/A	
ó .	Total numbers on each floor	N/A	N/A	N/A	
	 Length of hose reel hose 	N/A		N/A	
	Nozzle diameter	N/A	N/A	IN/A	
	Automatic fire detection and alarming	system		N/A	
7.	Automatic fire detection and distance of	N/A	N/A	AND DESCRIPTION OF THE PROPERTY OF THE PROPERT	
	Type of detectorsLocation of Main Panel	N/A	N/A	N/A	
	Location of Ividii Failer Location of Panastar Panal	N/A	N/A	N/A	
	Location of Repeater Panel A section of Repeater Panel The se	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location		27/4	N/A	
0	MOEFA	N/A	N/A	19/71	
8.		N/A	N/A	N/A	
9.	Public Address System	N/A	11/12		
10.	Automatic Sprinkler System				
10.		N/A	N/A	N/A	
	Basement	N/A	N/A	N/A	
	Ground Floor	District of the second	N/A	N/A	
	Sprinkler above false ceiling	N/A	14/11		
11.	Internal Hydrants				
11.		N/A	N/A	N/A	
	 Size of riser/down-comer 	N/A	N/A	N/A	
	 Number of hydrants per floor 	N/A	N/A	N/A	
	Hose Box	IN/A	1072		
12.	Yard Hydrants) N/A	
	Total number of hydrants	N/A	N/A	N/A	
		N/A	N/A	N/A	
12	Hose Box Pumping Arrangements				
13.					
	Ground Level	N/A	N/A	N/A	
	> Discharge of main Pump		N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A		N/A	
	Jockey Pump out putJockey pump head	N/A	N/A	N/A	
	U. D. and but put	N/A	N/A		
	= 114	N/A	N/A	N/A	
	/ 0.0	N/A	N/A	N/A	
	> Auto Starting/Manual		The second secon		

N/4

Building is comprised of Basement, Stilt, Upper ground, First floor & Second Floor. (Janak Guest House, C-2/6, Janakpuri, New Delhi – 110058)

20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			
- t	Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Detector System PanelFlow Switch Panel	N/A	N/A	N/A			
19.	Fire Control Room	NI/A	NT/A	21/4			
	E' C () I D	N/A	N/A	N/A			
	Total AreaLocation	N/A	N/A	N/A			
18.	Refuge Area.						
17.	Standby power supply	Required	Provided (15 KVA)	M/R			
.2° 8°		N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Pressurization of Lift lobbyCommunication In lift Car	N/A	N/A	N/A			
	Pressurization of Lift Shaft Pressurization of Lift Sahbur	N/A	N/A	N/A			
16.	Provision of Lifts.			(No Lift)			
15.	Exit Signage.	Required	Flovided	M/R			
		N/A Required	N/A Provided	N/A M/P			
	Overhead Tank capacity		N/A	N/A			
	> Access to tank	N/A N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	 Underground tank capacity Draw-off connection 	N/A	N/A	N/A			
14.	Captive Water Storage for fire fighting						
	That starting or pump	N/A	N/A	N/A			
	Auto Starting of pump	N/A	N/A	N/A			
	Head of the pumpPower Supply	N/A	N/A	N/A			
*	 Discharge of pump Head of the pump 	N/A	N/A	N/A			
	Pump House AccessTerrace level	N/A	N/A	N/A			
	Stopping	N/A	N/A	N/A			





The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note: As per the letter submitted by the owner of guest house (placed at C- 8 & 10), the year of construction of the building is before 2005 (The photocopy of property tax is placed at C-7) and there are only 14 guest rooms (The photocopy of Luxuries tax at C-9).

25/6/11

Signature of Inspecting Officer

Name: - S.K. Tomar

Designation:- Divisional Officer

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation:- Asstt. Divisional Officer

Dy.CFO (South Zone)

