GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

NO. F6/DF3ms/2016/1748

Dated: 05.12.2016

FIRE SAFETY CERTIFICATE

(Vipin Kental)

Chief Fire Officer

T.No.011-23412225

Copy to:- 1. Joint C.P. Licensing, 1st Floor, Police Station, Defence Colony, New Delhi.

2. M/s Taksim Dilli (A Unit of SVS Hospitality) locted at CG-001GF and CG-101 FF, Ansal Plaza Shopping Arcades at Hudco Place at Pinjra Pole, Andrewsganj, New Delhi.

Conditions for the validity of fire safety certificate are as under:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. The employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All fire fighting equipments shall be maintained in perfect working condition all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate, six month prior to its expiry.

1	4

1	INSPECTION REPORT FOR ANSA Name & address of the building	M/s Taksim Dilli (A Unit of SVS	Hospitality) locted at CG-00)1GF and CG-		
		101 FF, Ansal Plaza Shopping Arcades at Hudco Place at Pinjra Pole, Andrewsganj, New Delhi.				
,	Type of Occupancy	Assembly Occupancy Group-D(Eating House)				
2	Type of Geograms)	Two tier basements, Ground Mezzanine plus three upper floors. But				
3		restaurant is at ground, mezzanine and first floor only.				
4	11,000,000	New/Renewal (Now it is in new name)				
5	Botano or provident	No. F6/MS/DFS/EH/2014/SZ/147, Dated 30.01.2014.				
6	The salety directives letter 145	Nil.				
7	Date of Inoposition	30.11.2016.				
8	Name of the inspecting Officers	ADO Vedpal Sh. Vijay Alagh, Owner.				
9	I tallie alla accigi	On. Vijay Alagn, Owner.				
10	from the building side Year of construction	1997-1999				
10	Applicant's letter No.	43351-53/Jt.CP/Lic/EH(DA-I), dated 26.10.2016.				
11	, , , , , , , , , , , , , , , , , , , ,	Requirements /Existing Provided at site Remarks				
NO.	Minimum Standards on fire prevention and fire safety U/R 33	Fire Protection System as per Old NOC		MR / NMR		
1	Access to building		12m	MR		
-	1) Road width	1 togail ou	5m	MR		
	Sate width Width of internal road	Required	Provided as per approved	MR(old case)		
	9		plans			
2	Number, width Type & arrangement a. Number of staircases	nt of exits				
	Number of staircases Upper floors	02Nos.	03Nos (01no from inside & 02nos near the restaurant)	MR		
	2. basements	N/A	N/A	N/A		
	b. Width of staircase					
	1. Upper floors	Required	1.30m, 1.46m & 1.36m	MR(old case)		
	2. basements	N/A	N/A	N/A		
	c. Protection of exits					
	1. Fire check door	Required	Provided	MR		
	2. Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircase to terrace	Required	04Nos(One in A Block, One in B Block & Two in C Block)	e MR(old case)		
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	2m & 90cm (two at each level)	2m & 90cm (two at each level)	MR(old case		
3	Compartmentation.					
	1. Fire check door	Required	Provided	MR		
	2. Sealing of electrical shafts	Required	Provided	MR		
	3. Fire Rating of shaft door	Required	Provided	MR N/A		
	4. water curtain	N/A	N/A			
	5. Fire dampers	N/A	N/A	N/A		
4	Smoke Management system.	30 a/c per hour	1	N/A		
	Basement	12 a/c per hour	N/A Exhaust Fans Provided			
	Upper floors		2.310001 010 1 1011000	MR		
5	Fire Extinguishers	06Nos	06 Nos.Provided	MR		
	total numbers	ABC, CO2, WCO2	ABC, CO2, Water CO2,	MR		
	Types	ISI	Provided	MR		
6	ISI marking First-Aid Hose Reels.		mon for entire mall building)	1		
Ö	Total numbers on each floor	02nos.(Near restaurant)	02nos (Near restaurant)	MR		
		30 Mtr	30 Mtr Provided	MR		
	Length of Hose reel hose	5mm	5 MM Provided	MR		

	Type of detectors	Smoke & Heat	Smoke & Heat	MR			
	location of Main Panel	Ground Floor	Ground Floor	MR			
		N/A	N/A	N/A			
	location of Repeater panel	Required	Provided	MR			
	Alternate source of power	Required	All Areas	MR			
	hooter's location MOEFA	Required	Provided	MR			
		Required	Provided	MR			
0	Public Address System. Automatic Sprinkler System.	(Fire fighting system is com	nmon for entire mall building)				
)	basement	N/A	N/A	N/A			
	upper floors	Required	Provided	MR			
	sprinkler above false ceiling	N/A	N/A	N/A			
1	Internal Hydrants	(Fire fighting system is con	nmon for entire mall building)				
-	Size of riser/down-corner	150 mm	150mm Provided	MR			
	Number of Hydrants per floor	02nos. (Near restaurant)	02nos (Near restaurant).	MR			
	hose Box	02nos. (Near restaurant)	02nos. (Near restaurant)	MR			
2	Yard Hydrants.	(Fire fighting system is con	nmon for entire mall building)				
_	total number of hydrants	08 Nos	08 Nos. Provided	MR			
	house box	08 Nos.	08 Nos. Provided	MR			
3	Pumping arrangements (Fire figl		r entire mall building)				
-	1. Ground level						
	a. Discharge of main Pump	Required	4050 LPM Provided	MR			
	b.Head of main pump	Required	90m	MR			
	c.Number of main pumps	Required	02nos.	MR			
	d.jockey pump out put	Required	450LPM	MR			
	e.jockey pump head	Required	90m	MR			
	f. Standby Pump output	Required	8100 LPM Provided	MR MR			
	g.Stanby Pump head	Required	90m				
	h.Auto Starting/Manual stopping	Required	Provided	MR MR			
	pump house access	Required	Provided	IVIR			
	2.Terrace level	21/2	NI A	N.A.			
	a. Discharge of pump	N/A	N.A.	N.A.			
	b. head of the pump	N/A N/A	N.A.	N.A.			
	c. Power supply	N/A	N.A.	N.A.			
14	d. Auto starting of pump N/A N/A N.A. (Fire fighting system is common for entire mall building)						
	fighting						
	Underground tank capacity	450000 ltr	4,50,000 Ltr Provided	MR			
	a. Draw-off connection	Required	Provided	MR			
	b. fire service inlet	Required	Provided	MR			
	c. Access to tank	Required	Provided 20,000 ltrs on AB Block &	MR MR			
	d. Over head tank Capacity	20,000 ltr	30000 Itrs on C Block	TVII X			
15	Exit Signage.	Required	Provided	MR			
16	Provision of lifts.						
	a. Pressurization of lift shaft	N/A	N/A	N/A			
	b. Pressurization of lift lobby	N/A	N/A	N/A			
	c. Communication in lift car	Required	Provided	MR			
	d. Fireman's grounding switch	Required	Provided	MR			
	e. Lift signage	Required	Provided	MR			
17	Standby power supply	Required	DG Set Provided	MR			
18	Refuge Area.		INI/A	INI/A			
	total area	N/A	N/A	N/A			
	location N/A N/A N/A N/A						
19	Fire control room (Fire fighting system is common for entire mall building) a Detector system Panel Required Provided MR						
	a. Detector system Panel	Required	N/A	N/A			
	b. Flow switch Panel	N/A Required	Provided	MR			
	c. PA system Panel	Required	Provided	MR			
	d. Batter backup e. Building floor plans	N/A	N/A	N/A			

12/1

A

1/8

20 Special Fire Protection systems for protection of special risks, if any:
CO2 & ABC Type Fire Extingushers Provided near Electric Panel=MR

The fire protection systems provided in the building were checked and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/MS/DFS/EH/2014/SZ/147, dated 30.01.2014 renewal under rule 37 of the Delhi Fire Service Accordingly DFA is recommended.

Accordingly DFA is put up for kind consideration please

Signature of the inspecting officer

Name: Vedpal

Designation: ADO(SJ)

DO. (SD)

Dy (SO(52)

1/1/2

Cho 6.7/

W 2/12