GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

No. F.6/DFS/MS/EH/2016/SZ//757

Dated: 06-12-2016

FIRE SAFETY CERTIFICATE

Certified that the "Wok-in-the Clouds" (A unit of KTG Hotels & Resorts Pvt. Ltd.), J- 2/13, Rajouri Garden, New Delhi-110027, comprised of basement, ground plus three upper floors but restaurant is running at ground plus three upper floors owned/occupied by KTG Hotels & Resorts Pvt. Ltd.was issued Fire Safety Certificate by this department vide Letter No. F6/DFS/MS/EH/2013/WZ/1092 dated 15.10.2013. The Restaurant building was re-inspected by the officer concerned of this department on 10.11.2016 in the presence of Sh. Nitin (Duty Manager) and found that the KTG Hotels & Resorts Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises is fit for occupancy class Group D-6 assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on. 06-12-2016 at New Delhi.

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

- Sh. Vipin Kumar (Director),
 "Wok-in-the Clouds" (A unit of KTG Hotels & Resorts Pvt. Ltd.),
 J- 2/13, Rajouri Garden, New Delhi-110027.
- Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Building is comprised of Basement, ground floor plus three upper floors. But the restaurant is running at ground plus three upper floors. **INSPECTION REPORT** "Wok-in-the Clouds" (A unit of KTG Hotels & Resorts Pvt. Ltd.), J-Name & address of the building: 2/13, Rajouri Garden, New Delhi-110027 Type of Occupancy 2. Group D (Assembly) 3. Type of Case Renewal 4. Details of Previous NOC F6/DFS/MS/EH/2013/WZ/1092 dated 15.10.2013. Fire Safety directives letter No: F-22/H/TSM/2004/146/533 dated 13.06.2005 Date of inspection 10.11.2016 Name of Inspecting Officer A.D.O. Sandeep Duggal Name and designation of officers From the building side Sh. Nitin (Duty Manager) Year of Construction 2004-2005 10. Applicant's letter No. Nil dated Nil S. Minimum Standards on fire prevention and Requirement as Provided at site Remarks No. fire safety U/R 33 per FSC dt. MR/NMR 15.10.2013 1. Access to building Accessible(06 mtrs) 09 mtrs M/R Road width Old case 1.1 mtrs M/R, being old case Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors M/R Two Two Basements M/R Two Two b. Width of staircases 110 & 87 cms. M/R, being old case Two staircases Upper Floor 110 & 87 cms. M/R, being old case Two staircases Basements c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to M/R Required One terrace N/A (staircase N/A N/A Width of Corridor directly opening in Door Size f. halls) M/R, being old case 90 cms (02 no.'s) Two exits 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A (Restaurant is running at ground plus three upper floors) **Smoke Management System** 4. M/R Exhaust Fans are Required Basements Provided M/R Natural Required Upper floors Ventilation (Restaurant is running at ground plus three upper floors) Fire Extinguishers 5. M/R Provided 25 no.'s Total numbers WCO2/ABC/CO2 M/R Provided Types ISI marked M/R ISI marked IS marking (Restaurant is running at ground plus three upper floors) **First-Aid Hose Reels** 6. M/R Provided One Total numbers on First Floor

	A			0		
7.	Automatic fire detection and alarming system (Restaurant is running at ground plus three upper f					
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel Alternate source of records	N/A N/A	N/A	N/A		
	Alternate source of powerHooters' Location	N/A	N/A	N/A		
			N/A	N/A		
8.	MOEFA	Required	Provided	M/R		
9.	Public Address System	Required	Provided	M/R		
10.	Automatic Sprinkler System	(Restaurant is rur	nning at ground plus	three upper floors)		
	• Basement	Required	Provided	M/R		
	• First Floor	N/A	Provided	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants	(Restaurant is run	nning at ground plus	three upper floors)		
	Size of riser/down-comer	100 mm	Provided	M/R		
	Number of hydrants	One	Provided	M/R		
4.0	Hose Box	One	Provided	M/R		
12.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A		
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Standby Dump Hag J	N/A	N/A	N/A		
	Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A		
-	Samening mandar Stopping					
	Pump House Access	N/A	N/A	N/A		
	Terrace level	450 LPM & 225	Provided	M/R		
	Discharge of pump	LPM	i iovided	IVI/ IX		
20	Head of the pumpPower Supply	40 mtrs.	Provided	M/R		
	> Auto Starting of pump	Required	Provided	M/R		
		N/A	N/A	N/A		
14.	Captive Water Storage for fire fighting	1		×		
	Underground tank capacity					
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	Provided (02 way)	N/A		
	Access to tank Overhead Tank capacity	N/A	N/A	N/A		
	Overhead Tank capacity	5000 Ltrs.	Provided	M/R		
		Required	Provided	M/R M/R		
15.	Exit Signage.	1	- 10 / 1000	174/10		
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby Communication Lift Communication	N/A	N/A	N/A		
	Communication In lift Car Fireman's Grounding Switch	Required	Provided	M/R		
	Fireman's Grounding Switch	Dogwined	D 1	1.670		

18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19.	Fire Control Room	ÿ.		
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System PanelBattery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of	N/A	N/A	N/A
	special Risks, if any:			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F6/DFS/M\$/EH/2013/WZ/1092</u> dated <u>15.10.2013</u> renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

D.O.(South West)