

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No.F6/MS/DFS/SZ/EH/2016/ 146

Dated: 20/01/16

FIRE SAFETY CERTIFICATE

Certified that the Bikanerwala International,(Formerly Le-Forum) located at 7,Masjid Moth, Greater kailash -II, New Delhi-110048 comprised of Basement, Ground and Two Upper Floors owned/occupied by Bikanerwala International was issued FSC by this department vide letter no. F6/DFS/MS/EH/2011/21 dated 6/1/2011.The premises was re-inspected by the officer concerned of this department on 13/01/16 in the presence of Mr. Kailash Pandey and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Assembly Building, Group – D with effect from....20/01/16....for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued -----20/01/16-----at New Delhi by.



(Dr. G. C. Misra)
Chief Fire Officer
Tel: 011-23414333

Copy to:-

- (1) The Authorised Signatory
Bikanerwala International
7,Masjid Moth,GK-II,
New Delhi-110048
- (2) The Dy. Health Officer,
SDMC, South Zone,
Aurobindo Marg, Green Park
New Delhi



Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of BBL.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- Bikanervala International, (Formerly Le-Forum Restaurant), 7, Masjid Moth, Greater kailash -II, New Delhi-110048.
2. Type of occupancy:- Assembly, Group – D, Restaurant
3. Type of case:- Renewal and name change
4. Details of previous NOC:- F6/DFS/MS/EH/2011/21 dated 06/01/20011
5. Fire safety directives No.- Nil
6. Date of inspection:- 13/01/2016
7. Name of the inspecting officer:- D.B. Mukherjee, A.D.O. (BCP)
8. Name & designation of officer from the building side:- Mr. Kailash Pandey (Manager)
9. Year of construction:- 2005
10. Applicant's letter no:- Nil, Dated 22/12/2015
- Building is comprised of :- Basement, Ground + Two Upper Floors.

Sl. No.	Minimum Standards on fire Prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at Site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	09 mtrs.	Provided	MR
	2) Gate width	Required	Approachable	MR
	3) Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors	02nos	Provided	MR
	2. Basements	02nos	Provided	MR
	B. Width of staircase			
	1. Upper floors	Required Old Case	0.92mtr, 1.10mtr	MR (Old Case)
	2. Basements	Required Old Case	0.92mtr, 1.10mtr	MR (Old Case)
	C. Protection of exits			
	1. Fire check door	Required	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	Required	02nos	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	Old Case	Provided 02 nos. 1.70mtr, 1.05	MR
3.	Compartmentation			
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 a/c per hour	Provided	MR
	2) Upper floors	12 a/c per hour	Provided	MR
5.	Fire Extinguishers			
	1) Total numbers	ISI Marked	10Nos.	MR
	2) Types		ABC, Co2	MR
	3) ISI marking		Yes	MR

6.	First-Aid Hose Reel			
	1) Total number of each floor	01	Provided	MR
	2) Length of hose reel hose	30 m	Provided	MR
	3) Nozzle diameter	5 mm	Provided	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Required	Provided	MR
	2) Location of main panel	GF	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Every Floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	1) Basement	Required	Provided	MR
	2) Upper floors	Required	Provided	MR
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	100mm	Provided	MR
	2) Number of hydrants per floor	01no	Provided	MR
	3) Hose box	01no	Provided	MR
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	450 Lpm	Provided 450 & 180 lpm	MR (Old Case)
	b) Head of pump	35mtr	Provided	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire Fighting			
	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	5000ltrs	Provided	MR (Old Case)
15.	Exit Signage.	Required	Removed	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A

N/15

17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area			
	Total area	N/A	N/A	N/A
	location	N/A	N/A	N/A
19.	Fire Control Room			
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The shortcomings issued vide letter no. F6/DFS/MS/EH/2015/2140 have been rectified. In view of the compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/EH/2011/21 dated 06/01/2011, renewal under rules 35 of the Delhi Fire Service Rules 2010 is recommended. Accordingly DFA is put up for sign pls.

18/11/2016

Signature of the inspecting officer
 Name :- D.B. Mukherjee.
 Designation :- Assistant Divisional Officer.

DO (South)