GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/EH/2016/ NP2 346

Dated: 03(97)(6

FIRE SAFETY CERTIFICATE

Certified that the M/s Masala Library Restaurant (A Unit of Massive Restaurant Pvt. Ltd.) located at 21-A,Ground Floor, Janpath, New Delhi building is comprised of Ground + 2 upper floor but restaurant is running on ground floor only more than 50 seats have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 19/02/16 in the presence of Mr. Zorawar Inder Singh Kalra that the premises is fit for occupancy of class Assembly Building Group-D Restaurant with effect from ---(2-7-1-2-7-1-1)-1-1- for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, mentioned below.

(Dr. G. C. Misra) Chief Fire Officer Delhi Fire Service Ph – 011-23414333

- Copy to:- (1) Medical Officer of Health, New Delhi Municipal Council, Palika Kendra, New Delhi.
 - (2) Mr. Zorawar Inder Singh KalraM/s Masala Library (A Unit of Massive Restaurant Pvt. Ltd.),21-A,Ground Floor, Janpath,New Delhi.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building: M/s Masala Library Restaurant (A Unit of Massive Restaurant Pvt. Ltd.) at 21-A, Ground

Floor, Janpath, New Delhi.

Assembly Building Group D, Ground + 2 2. Type of occupancy:-

upper floor (restaurant is on ground floor)

only

3. Type of case:-New

No.

4. Details of previous FSC: -5. Fire safety directives No.-

N/A

6. Date of inspection:-

19/02/16

7. Name of the inspecting officer:-

D.O. Gurmukh Singh &

A.D.O. Manoj Kumar Sharma

8. Name & designation of officer From the building side:-

Mr. Zorawar Inder Singh Kalra

9. Year of construction:-

1990.

10. Applicant's letter No:-

Nil dated 25/01/16

.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR
	Access to Building	No.		
	1) Road width	6 mtr.	18 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	NA	NA	NA
	Number, Width Type & Arrange			
2.	A. Number of staircases	5		
	1. Upper floors	NA	NA	NA
	2. Basements	NA	NA	NA -
	B. Width of staircase			
	1. Upper floors	NA	NA	NA
	2. Basements	NA	NA	NA
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	N/A
	staircase to terrace			-32
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	2 Mtr. & 1	2 Mtr. & 2.5	MR
	1. Boot size	Mtr.	Mtr.	
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
т.	1) Basements	30 ACPH	NA	NA

W-47

121				96		
	2) Upper floors	12 ACPH	Natural	MR		
5.	Fire Extinguishers			IVIIC		
	1) Total numbers	06 Nos.	08 Nos.	MR		
	2) Types	ABC & CO2	ABC, CO2 &			
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel	1	Trovided	IVIK		
	1)Total number of each	01 no.	01 no.	MR		
	floor	н	01 HO.	MIK		
	2) Length of hose reel hose	30 Mtr.	30 Mtr.	MR		
	3) Nozzle diameter	5 mm	5			
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	N/A	NT/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	N/A		
).	Public Address System	N/A		MR		
	/Intercom	I W/A	N/A	N/A		
0.	Automatic Sprinkler System					
	1) Basement	N/A	NI/A	2.71		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling	IN/A	N/A	N/A		
1.	Internal Hydrants					
	1) Size of riser/down-comer	100 mm.	100			
	2) Number of hydrants per	01 no.	100 mm.	MR		
	floor	01 110.	01 no.	MR		
	3) Hose box	01 no.	01			
2.	Yard Hydrants	01 110.	01 no.	MR		
	1) 75	N/A	77/1			
	2) Hose box		N/A	N/A		
3.	Pumping Arrangement	N/A	N/A	N/A		
*	1) Ground level	27/1				
		N/A	N/A	N/A		
	, and a striction	N/A	N/A	N/A		
	b) Head of main pump	77/4				
	, and the pump	N/A	N/A	N/A		
	, and that pump	N/A	N/A	N/A		
	y penipout put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping			-		
	2) Terrace level					
	a) Discharge of pump	450 LPM	450 LPM	MR		
-	b) Head of pump	40 Mtr.	40 Mtr.	MR		
	c) Power supply	Required	Provided	MR		

N/5

	d) Auto starting of pump		Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	1) Under ground tank capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	10,000 Ltr.	10,000 Ltr.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection System any:	N/A				

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, grant of fire Safety Certificate, under rule 35 of the Delhi Fire Service Rules 2010, is recommended please.

Gurmukh Singh Divisional Officer

Manoj Kumar Sharma Assistant Divisional Officer

Mersh

Dy CRO (402)

23/2-1

28/2 Loit alive 50 leab-?

CAO POST SIN