GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

E-mail: gargatul@hotmail.com, Tel:- 011-26189168

NO.F6/DFS/MS/GH/2016/ 52/969

Dated:

08/06/16

FIRE SAFETY CERTIFICATE

Issued on 68/06/16 at New Delhi by.

(ATUL GARG) CHIEF FIRE OFFICER

Copy to: -

1. The Joint C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

2. The Manager, Tavisha Guest House, C-18, New Friends Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate

a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.

b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.

c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.

d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Tavisha guest house, C-18, Friends Colony East, New Delhi

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : Letter No. F.6/DFS/MS/GH/2013/453 dated: 19.06.2013

5. Fire Safety directives letter No : Nil

6. Date of inspection : 01-06-2016

7. Name of the Inspecting Officers: M.K.Chattopadhyay, ADO(M.Rd)

8. Name and designation of officers

from the building side : Mr. Dhirender Saini, Manager

9. Year of Construction : 2009

10. Applicant's letter No. : 1097/Addl. C.P/Lic.(H) dated 13.05.2016

The said guest house is comprised of basement (lying vacant + pump room), stilt/lower ground (reception + parking), upper ground floor (12 guest rooms + pantry), first floor (15 guest rooms), second floor (15 guest rooms) and third floor (15 guest rooms)

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mts	6.10 mts	MR		
	• Gate width	-	Directly accessible from the street	MR		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		-	_		
	Upper Floors	02	02	MR		
	Basements	02	02	MR		
	b. Width of staircases	_	- 4	-		
	Upper Floors	1.25 mts, 0.92 mts	provided	MR		
	Basements	1.25 mts, 0.92 mts	provided	MR		
	c. Protection of exits	N/A	N/A	N/A		
	Fire check door	N/A	N/A	N/A		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	01	01	MR		
	g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	N/A	N/A	N/A		
	Compartmentation.		· · · · · · · · · · · · · · · · · · ·			
	• Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	• Fire Rating of shaft door	N/A	N/A	N/A		
- 1	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
A P	Smoke Management System.					
	• Basements	30 a/c per hour	Exhaust fan provided	MR		
	Upper floors	12 a/c per hour	Provided	MR		

	Types	ABC,WCO ₂ , CO ₂	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.	*				
	Total numbers on each floor	01	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming					
	Type of detectors	Smoke/Heat	· Provided	MR		
	Location of Main Panel	Required	Provided	MR		
	Location of Repeater Panel	Required	Provided	MR		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Near staircase	Provided	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	Automatic Sprinkler System.	Automatic Sprinkler System.				
	Basement	Required	Provided	MR		
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	• Size of riser/down-comer	100 mm	Provided	MR		
	Number of hydrants per floor	01	Provided	MR		
	Hose Box	01	Provided	MR		
12	Yard Hydrants.					
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	Ground Level	- · · · · · · · · · · · · · · · · · · ·	-	-		
	Discharge of main Pump	450 LPM	Provided	MR		
	Head of Main pump	40 mts	Provided	MR		
	Number of main pumps	01	Provided	MR		
	Jockey Pump out put	180 LPM	Provided	MR		
3.5	Jockey pump head	40 mts	Provided	MR		
700	> Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	> Auto Starting/ Manual	N/A	N/A	N/A		
	stopping	.80	ed painers with	IV/A		

1	Discharge of pump	900 LPM	Provided	MR				
	> Head of the pump	40 mt	Provided	MR				
	Power Supply	Required	Provided	MR				
	> Auto Starting of pump	Required	provided	MR				
14	14 Captive Water Storage for fire fighting.							
	Underground tank capacity	35000 lts	Provided	NR				
	Draw-off connection	Required	Provided	MR				
	Fire service inlet	Required	Provided	MR				
	> Access to tank	N/A	N/A	N/A				
	Overhead Tank capacity	10000 liters	Provided	MR				
15	Exit Signage.	Required	Provided	MR				
16	Provision of Lifts.							
	Pressurization of Lift Shaft	N/A	N/A	N/A				
	Pressurization of Lift lobby	N/A	N/A	N/A				
	Communication In lift Car	N/A	N/A	N/A				
	Fireman's Grounding Switch	N/A	N/A	N/A				
	• Lift Signage	N/A	N/A	N/A				
17	Standby power supply	Required	Provided (02 D.G set- 200KVA, 62.5 KVA)	MR				
18	Refuge Area.							
	> Total Area	N/A	N/A	N/A				
	> Location	N/A	N/A	N/A				
19	Fire Control Room							
	Detector System Panel	N/A	N/A	N/A				
	• Flow Switch Panel	N/A	N/A	N/A				
	PA System Panel	N/A	N/A	N/A				
	Batter backup	N/A	N/A	N/A				
1	Building Floor Plans	N/A	N/A	N/A				
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two CO ₂ type fire extinguishers found provided near elect. panel	MR				

The fire protection systems provided in the building were tested and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/GH/2013/453 dated: 19.06.2013, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

DCF o (D.p. Bhardway)

15/16/16·

M.K.Chattopadhyay
ADO (MRD)