GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

Dated: 14/10/16

FIRE SAFETY CERTIFICATE

Certified that the M/s Hilton Garden Inn at, DLF Place Mall, A-4 Distt. Centre, Saket, New Delhi-110017 comprises of three tiers Basement, Ground floor + 7 Upper floors but the Hotel is from 2nd floor to 7th floor was granted FSC by this department vide letter No. F6/DFS/MS/GH/2013/SZ/964 dated 24/09/13. The premises was re- inspected by the officers concerned of this department on 22/09/16in the presence of Mr. Rahul (Fire Officer) & Mr. Ravinder (Chief Engineer) of the hotel and observed that fire safety norms as required under Rule 33 of Delhi Fire Service Rules, 2010 are complied and that the premises is fit for occupancy class Group- A "Hotel Building" with effect from Later-2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on at New Delhi by.

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

de t

Copy to:-

1. Mr. Ravinder (Chief Engineer), Hilton Garden Inn, DLF Place Mall, A-4 Distt. Centre, Saket, New Delhi-110017

2. The Joint Commissioner of Police (Lic.), First Floor, Police Station, Defence Colony, New Delhi

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1. Name & address of the building: M/s Hilton Garden Inn, DLF Place Mall, A-4 Distt. Centre, Saket, New Delhi-110017 :Group A "Hotel Building" [Building is 3B+G+7 upper floors]
: Renewal [Hotel is running at 2nd floor to 7th floor only] 2. Type of Occupancy 3. Type of Case 4. Details of Previous NOC: F6/DFS/MS/GH/2013/SZ/964 dated 24/09/13 5. Fire Safety directives letter No: F6/DFS/MS/2010/2095 dated 15/07/13 : 22/09/16 6. Date of inspection : A.K. Malik 7. Name of Inspecting Officer 8. Name and designation of officers : Mr. Rahul (Fire Officer) & Mr. Ravinder (Chief Engineer) From the building side : 2009 9. Year of Construction : Outdoor diary No. 8603 dated 30/08/2016 10. Applicant's letter No. Remarks Provided at site Minimum Standards on fire prevention NBC/BBL S. MR/NMR Requirement and fire safety U/R 33 No. Access to building[DLF Place Mall FSC No. of F6/DFS/MS/2015/Mall/SZ/1954 dated 30/10/15] 1. MR As Above Hotel within Mall Road width Gate width Width of internal road Number, Width, Type & Arrangement of Exits[Provided & Maintained by Mall management] 2. a. Number of staircases MR Hotel within Mall 2 No's Upper Floors NA As Above Hotel within Mall Basements Hotel within Mall b. Width of staircases MR 1.5m Hotel within Mall Upper Floor NA As Above Hotel within Mall Basement Hotel within Mall c. Protection of exits MR Provided Hotel within Mall. Fire check door MR Provided Hotel within Mall Pressurization MR 2 No's Hotel within Mall d. No. of continuous staircases to terrace MR 1.5m Hotel within Mall e. Width of Corridor MR 1m (Final Exit) 1m Door Size Compartmentation 3. MR Provided Required Fire check door MR Provided Required Sealing of electrical shafts MR Provided Fire Rating of shaft door Required NA Water Curtain NA NA MR Provided Fire Dampers Required Smoke Management System[Provided & Maintained by Mall management] 4. MR As Above 30 ACPH Basements MR As Above 12 ACPH Upper floors Fire Extinguishers 5. MR Total-90 No's 50 No's Total numbers MR ABC-40 No's ISI marked Types CO₂/W.CO₂-50 No's MR IS marking First-Aid Hose Reels[Provided & Maintained by Mall management] 6. MR Provided Two No's Total numbers on each floor Provided MR 30 m Length of hose reel hose MR 5 mm Provided Nozzle diameter Automatic fire detection and alarming system[Provided & Maintained by Mall management] 7. MR Smoke & Heat Required Type of detectors MR Required Sec. Control Room Location of Main Panel Required MR Provided Location of Repeater Panel Required MR Provided Alternate source of power Required MR All Floors Hooters' Location MR Provided Required **MOEFA** 8. MR Provided Required **Public Address System** Automatic Sprinkler System[Provided & Maintained by Mallmanagement]

	Ground Floor	Required	Provided	MR
	 Sprinkler above false ceiling 	Required	Provided	MR
11.	Internal Hydrants[Provided & Maintained			
	Size of riser/down-comer	100mm	100mm	MR
	 Number of hydrants per floor 	Two	Provided	MR
	Hose Box	Two	Provided	MR
2.	Yard Hydrants[Provided & Maintained by			
	 Total number of hydrants 	Hotel within Mall	Provided	MR
	Hose Box	Hotel within Mall	Provided	MR
3.	Pumping Arrangements[Provided & Main	tained by Mall manage	ement]	
	Ground Level			
	Discharge of main Pump	Hotel within Mall,		MR
	> Head of Main pump	Hotel within Mall	Provided	MR
	Number of main pumps	Hotel within Mall	Provided	MR
	> Jockey Pump out put	Hotel within Mall	Provided	MR
	Jockey pump head	Hotel within Mall	Provided	MR
	Standby Pump out put	Hotel within Mall	Provided	MR
	Standby Pump Head Auto Starting Manual Stanning	Hotel within Mall	Provided	MR
	Auto Starting/Manual StoppingPump House Access	Hotel within Mall	Provided	MR
	Terrace level	Hotel within Mall	Provided	MR
	Discharge of pump	[Provided & Maintained by Mall manageme		nagement]
	Head of the pump	Hotel within Mall	Provided	MR
	> Power Supply	Hotel within Mall	Provided	MR
	➤ Auto Starting of pump	Hotel within Mall	Provided	MR
		Hotel within Mall	Provided	MR
4.	Captive Water Storage for firefighting[Pr	47		
	 Underground tank capacity 	Hotel within Mall	Provided	MR
	Draw-off connection	Hotel within Mall	Provided	MR
	Fire service inlet	Hotel within Mall	Provided	MR
	Access to tank	Hotel within Mall	Provided	MR
	Overhead Tank capacity	Hotel within Mall	Provided	MR
5.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.[Provided & Maintained			
	Pressurization of Lift Shaft	Hotel within Mall	Provided	MR
	Pressurization of Lift lobby	Hotel within Mall	Provided	MR
	Communication In lift Car	Hotel within Mall	Provided	MR
		Hotel within Mall	Provided	MR
	Fireman's Grounding SwitchLift Signage	Hotel within Mall	Provided	MR
7.	Standby power supply	Required	Provided	MR
8.	Refuge Area. [Provided & Maintained by M		1 TOVIDEU	IVIN
J.	Total Area	Required	110 m ²	MR
	> Location	Required	4 th , 5 th & 6 th Floor	MR
9.	Fire Control Room[Provided & Maintained	1		IVIIX
	Detector System Panel	Required	Provided	MR
	Flow Switch Panel	Required	Provided	MR
	The state of the s	Required	Provided	MR
	PA System PanelBatter backup	Required	Provided	MR
	Building Floor Plans	Required	Provided	MR
	Dunding Floor Flairs	required	Tiovided	IVIIC
0.	Special Fire Protection System for I	Dungto odie C . 1	Diales if	NA

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, It is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly FSC in shape of DFA is put up for approval.

Signature of Inspecting Officer

Name: - A.K. Malik Designation:- DO (SD)

Spoken on 4/10/16, the Main flery
Noll is enclosed.